

WSDOT Local Programs
Federal Local Bridge Program
Project Application

Skagit County _____
 AGENCY

4/26/2022 _____
 DATE

Forrest Jones _____
 AGENCY CONTACT

360-416-1422 _____
 PHONE

forrestj@co.skagit.wa.us _____
 EMAIL

Torey Nelson _____
 BRIDGE CONTACT

360-416-1425 _____
 PHONE

toreyn@co.skagit.wa.us _____
 EMAIL

Project Type *Check all that apply.*

- Replacement Candidate
- Rehabilitation Candidate
- Preventative Maintenance
- Scour Mitigation
- Seismic Retrofit
- Painting
- Deck Repair
- Other *(applicable for Bundled Projects only)*
- Bundled Project
- Construction Ready Project

Project Description

Provide structure identification information. For bundled projects, list all structures included.

STRUCTURE ID	BRIDGE NUMBER	BRIDGE NAME
08228800	40070	SKAGIT RIVER MARBLEMOUNT
_____	_____	_____
_____	_____	_____
_____	_____	_____
_____	_____	_____
_____	_____	_____

Provide a brief project description, including bridge replacement type if applicable.

The project consists of rehabilitating deficient elements of the 92 year old structure, including gusset plate replacement, cleaning and painting of the bridge, sealing and caulking of pack rust, expansion joint replacement, bearing repair, structural steel repair, and approach railing replacement.

Provide additional applicable details for replacement or full deck rehabilitation project.

PROPOSED LENGTH

PROPOSED CURB TO CURB WIDTH

Will this project...check all that apply and provide description

- Mitigate current bridge posting
The load rating calls for posting of all legal loads due to the deficiencies of structural steel elements. Rehabilitation will mitigate the current posting requirements and allow for the crossing of legal loads.
- Remove scour critical coding
- Mitigate other bridge restriction
Bridge is restricted to a 1-lane, 2-way operation. Rehabilitation will restore 2-lane, 2-way operation.
- Require in-water construction work
- Require stormwater drainage

Project Cost

Replacement, Rehabilitation, Seismic Paint, or Scour projects

PE Costs (approximately 25% of total)	\$ 3,718,573
<i>Soils, environmental, design documents, plans preparation, etc.</i>	
Right of Way Costs	
<i>Purchases, relocation and construction easement</i>	
Construction Costs	
<i>Environmental mitigation, approach costs (15%), structure costs, etc.</i>	\$ 9,705,900
Construction Engineering (18%)	\$ 1,747,062
Contingency (15%)	\$ 1,455,885
Mobilization (10%)	\$ 970,590
Inflation Cost (5% per year, based on projected ad date)	\$ 994,855
TOTAL COST	\$ 18,592,865

Other Preventative Maintenance projects

TOTAL COST _____

If a Rehabilitation project, what would be the Replacement cost for that same structure, including PE, right of way, and construction?

Similar Replacement Cost \$ 23,500,000

Local Agency Match Funds

- | | |
|---|--|
| <input checked="" type="checkbox"/> Agency is prepared to match funds | <input type="checkbox"/> Match funding is not secured |
| <input type="checkbox"/> Other funding sources have been secured | <input type="checkbox"/> Match funding is not required |

Project Milestones

	MM/YY		MM/YY
Project Added to Local Agency TIP	<u>12/20</u>	Right of Way Start	_____
Project Added to Regional TIP	<u>01/23</u>	Right of Way Complete	_____
Project Added to STIP	<u>02/23</u>	Geomtric/30% Design Complete	<u>09/23</u>
Project Definition Begin PE	<u>02/23</u>	General Plan/60% Design Complete	<u>03/24</u>
NEPA Kick Off	<u>04/23</u>	Advertisement	<u>09/24</u>
Environmental Docs Approved	<u>10/24</u>	Contract Awarded	<u>11/24</u>
		Open to Traffic	<u>10/25</u>

Comments or Additional Relevant Information

The SKAGIT RIVER MARBLEMOUNT bridge is a 1100 foot long structure constructed in 1930 consisting of three steel truss main spans (160':280':160') and 500 feet of reinforced concrete t-beam approach spans.

The bridge serves as a direct link to the N Cascades Hwy (SR 20) and is the one of the few crossings of the Skagit River available in the vicinity with the nearest downstream crossing approximately 9 road miles away and the nearest upstream crossing approximately 14 road miles away. The structure, in conjunction with the CASCADE RIVER BRIDGE, also serves as a link to the Washington State Department of Fish and Wildlife's Fisheries Department. In addition, this bridge also serves as a needed detour route for SR 20, as was evident during the extreme weather event that occurred in November of 2021 and a landslide that closed SR 20. The only available detour is to use the Marblemount Bridge to access the alternate route.

The structure currently has numerous deficient elements, including:

- Gusset plates in need of repair/replacement
- Bearings in need of repair
- Steel stringers and floor beams in need of repair



Application Checklist

- | | |
|--|---|
| <input checked="" type="checkbox"/> Completed Application | <i>If applicable for project type:</i> |
| <input checked="" type="checkbox"/> Bridge SI&A Sheet | <input checked="" type="checkbox"/> Load Rating Summary Sheet |
| <input checked="" type="checkbox"/> Current Inspection Report(s) | <input checked="" type="checkbox"/> Scour Analysis |
| <input checked="" type="checkbox"/> Electronic Photos | <input type="checkbox"/> Seismic Evaluation |



Skagit County Public Works

Table of Contents

Appendix A – Site Map

Appendix B – Bridge Inventory Data

Appendix C – Bridge Load Rating

Appendix D – In-Depth Inspections

Appendix E – Scour Evaluation

Appendix F – Traffic Data

Appendix G – Bridge Rehabilitation Cost Estimate




Skagit County Public Works

Appendix A – Site Map

VICINITY MAP
SKAGIT RIVER MARBLEMOUNT

#40070





Skagit County Public Works

Appendix B – Bridge Inventory Data

WASHINGTON STATE DEPARTMENT OF TRANSPORTATION
 NBI STRUCTURE INVENTORY AND APPRAISAL REPORT
 (ENGLISH UNITS)

CD Date: 3/22/2022 Printed on: 4/26/2022
 CD Guid: 089e8183-e033-44d8-a7f8-30898ae839c1

IDENTIFICATION				WSBIS DATA			
(1) STATE NAME - WASHINGTON			530	BRIDGE NUMBER			40070
(8) STRUCTURE NUMBER		# 082288000000000		BRIDGE NAME		SKAGIT RIVER MARBLEMOUNT	
(5) INVENTORY ROUTE (ON/UNDER) - On		1 4 1 97950		CUSTODIAN		Skagit County	
STATE ROUTE MILEPOST		0.03		CROSSING DESC		SKAGIT RIVER MARBLEMOUNT	
(2) HIGHWAY AGENCY DISTRICT - NW Region			01	MAIN LISTING FLAG		M	
(3) COUNTY CODE 57 - Skagit County		(4) PLACE CODE 99057		SUFFICIENCY RATING		32.38 SD	
(6) FEATURES INTERSECTED		SKAGIT RIVER		CLASSIFICATION			
(7) FACILITY CARRIED		CASCADE RIVER RD		(112) NBIS BRIDGE LENGTH			Y
(9) LOCATION		0.03 E JCT SR 20		(104) HIGHWAY SYSTEM - Not on the NHS			0
(12) BASE HIGHWAY NETWORK - Not part of network			0	(26) FUNCTIONAL CLASS - Minor Collector			08
(13) LRS INV ROUTE AND SUB ROUTE				(100) DEFENSE HIGHWAY - Not a STRAHNET route			0
(11) LRS MILEPOST				(101) PARALLEL STRUCTURE - Not a parallel bridge			N
(16) LATITUDE		48 Deg 31 Min 36.00 Sec		(102) DIRECTION OF TRAFFIC - 2-way traffic			3
(17) LONGITUDE		121 Deg 25 Min 48.00 Sec		(103) TEMPORARY STRUCTURE - Not Applicable			
(98A) BORDER BR. - Not a border bridge (98B) (99) BORDER BR. SID - Not a border bridge				(105) FEDERAL LANDS HIGHWAY - Forest Highway (FH)			2
STRUCTURE TYPE AND MATERIAL				(110) DESIGNATED NATIONAL NETWORK - Not part of network			0
(43) STRUCTURE TYPE MAIN: MATERIAL - Steel				(20) TOLL - Non-toll structure			3
DESIGN - Truss - Thru			310	(21) MAINTENANCE - Highway Agency			02
(44) STRUCTURE TYPE APPR: MATERIAL - Concrete				(22) OWNER - County Highway Agency			2
DESIGN - Channel beam			122	(37) HISTORICAL SIGNIFICANCE - Not eligible			5
(45) NO. OF SPANS IN MAIN UNIT			3	CONDITION			
(46) NO. OF APPROACH SPANS			2	(58) DECK			6
(107) DECK STRUCTURE TYPE - Conc. CIP			1	(59) SUPERSTRUCTURE			6
(108) WEARING SURFACE / PROTECTIVE SYSTEM:				(60) SUBSTRUCTURE			7
(A) TYPE OF WEARING SURFACE - Monolithic concrete			1	(61) CHANNEL AND CHANNEL PROTECTION			6
(B) TYPE OF MEMBRANE - None			0	(62) CULVERTS			N
(C) TYPE OF DECK PROTECTION - None			0	LOAD RATING AND POSTING			
AGE AND SERVICE				(31) DESIGN LOAD - H 15			2
(27) YEAR BUILT			1930	(63) OPER RATING METHOD - Load and Resistance Factor			3
(106) YEAR RECONSTRUCTED			0000	(64) OPERATING RATING			12 T
(42) TYPE OF SERVICE ON - Highway			1	(65) INV RATING METHOD - Load and Resistance Factor (LRFR),			3
UNDER - Waterway			5	(66) INVENTORY RATING			8 T
(28) LANES: ON STRUCTURE 1		UNDER STRUCTURE 0		(70) BRIDGE POSTING - 30.0 - 39.9% below legal load			1
(29) AVERAGE DAILY TRAFFIC			608	(41) STRUCT OPEN, POSTED, CLOSED - Posted for cap			R
(30) YEAR OF ADT 2020		(109) TRUCK ADT 11%		APPRAISAL			
(19) BYPASS, DETOUR LENGTH			20 mi	(67) STRUCTURAL EVALUATION			2
GEOMETRIC DATA				(68) DECK GEOMETRY			2
(48) LENGTH OF MAXIMUM SPAN			280 ft	(69) UNDERCLEARANCES, VERTICAL & HORIZONTAL			N
(49) STRUCTURE LENGTH			662 ft	(71) WATERWAY ADEQUACY			7
(50) CURB OR SIDEWALK: LEFT 0.0 ft		RIGHT 0.0 ft		(72) APPROACH ROADWAY ALIGNMENT			6
(51) BRIDGE ROADWAY WIDTH CURB TO CURB			14.0 ft	(36) TRAFFIC SAFETY FEATURES			1111
(52) DECK WIDTH OUT TO OUT			22.0 ft	(113) SCOUR CRITICAL BRIDGE			8
(32) APPROACH ROADWAY WIDTH (W/SHOULDERS)			20 ft	PROPOSED IMPROVEMENTS			
(33) BRIDGE MEDIAN - No median			0	(75) TYPE OF WORK -			311
(34) SKEW 0 Deg		(35) STRUCTURE FLARED No 0		(76) LENGTH OF STRUCTURE IMPROVEMENT			672 ft
(10) INVENTORY ROUTE MIN VERT CLEAR			17 ft 09 in	(94) BRIDGE IMPROVEMENT COST			\$8,299,000
(47) INVENTORY ROUTE TOTAL HORIZ CLEAR			20 ft 00 in	(95) ROADWAY IMPROVEMENT COST			\$1,660,000
(53) MIN VERT CLEAR OVER BRIDGE RDW			17 ft 09 in	(96) TOTAL PROJECT COST			\$16,598,000
(54) MIN VERT UNDERCLEAR			0 ft 00 in N	(97) YEAR OF IMPROVEMENT COST ESTIMATE			2022
(55) MIN LAT UNDERCLEAR RT			0.0 ft N	(114) FUTURE ADT			742
(56) MIN LAT UNDERCLEAR LT			0.0 ft	(115) YEAR OF FUTURE ADT			2040
NAVIGATION DATA				INSPECTIONS			
(38) NAVIGATION CONTROL - No nav control			0	(90) INSPECTION DATE 03/22		(91) FREQUENCY 24 MO	
(111) PIER PROTECTION - Not Applicable				(92) CRITICAL FEATURE INSPECTION:		(93) CFI DATE	
(39) NAVIGATION VERTICAL CLEARANCE			000 ft	(A) FRACTURE CRIT DETAIL - YES -		24 Month	(A) 03/22
(116) VERT-LIFT BRIDGE NAV MIN VERT CLR				(B) UNDERWATER INSP - NO -		Month	(B) __/__/__
(40) NAVIGATION HORIZONTAL CLR			0000 ft	(C) OTHER SPECIAL INSP - NO -		Month	(C) __/__/__

BRIDGE INSPECTION REPORT

Status: Work
 CD Guid: 089e8183-e033-44d8-a7f8-30898ae839c1

Printed On: 4/26/2022
 Release Date:

Agency: Skagit County
 Program Mgr: Sonia L. Lowry

Br. No. 40070	SID 08228800	Br. Name SKAGIT RIVER MARBLEMOUNT
Carrying CASCADE RIVER RD		Route On 97950 Mile Post 0.03
Intersecting SKAGIT RIVER		Route Under Mile Post

Inspector's Signature TKK Cert # G1303 Cert Exp Date 1/31/2027 Co-Inspector's Signature PFK

				Inspections Performed:			
Freq	Hrs	Date	Rep Type				
24	1.0	3/22/2022	Routine				
24	12.0	3/22/2022	Fract Crit				
				UW			
				Special			
				Interim			
				UWI			
				Damage			
				PRM Safety			
				SEC Safety			
				Condition			
				Short Span			
				In Depth			
				Geometric			

2	Structural Eval (1657)	12	Operating Tons (1552)	0	No Utilities (2675)		
2	Deck Geometry (1658)	0.32	Op RF (1553)	1	Bridge Rails (1684)		
9	Underclearance (1659)	8	Inventory Tons (1555)	1	Transition (1685)		
6	Alignment (1661)	0.22	Inv RF (1556)	1	Guardrails (1686)		
6	Deck Overall (1663)	1	Operating Level (1660)	1	Terminals (1687)		
6	Superstructure (1671)	R	Open/Closed (1293)	0.00	Asphalt Depth (2610)		
7	Substructure (1676)	7	Waterway (1662)		Design Curb Ht (2611)		
9	Culvert (1678)	8	Scour (1680)		Bridge Rail Ht (2612)		
6	Chan/Protection (1677)		Soundings Flag (2693)	1930	Year Built (1332)		
N	Pier/Abut/Prot (1679)		Revise Rating (2688)	0	Year Rebuilt (1336)		
7	Drain Cond (7664)		Photos Flag (2691)	Y	Subj to NBIS (2614)		
1	Drain Status (7665)		Measure Clrnc (2694)			Alpha Span Type: STrus	
M	Deck Scaling (7666)	9	Sdwk Cond (7673)			Sufficiency Rating: 32.38	
1	Scaling Pct (7667)	5	Paint Cond (7674)			Status: SD	
7	Deck Rutting (7669)	6	Approach Cond (7681)			Routine Risk Category: High Risk	
8	Exposed Rebar (7670)	9	Retaining Wall (7682)			Underwater Risk Category: No Risk Category	
9	Curb Cond (7672)	9	Pier Prot (7683)				

BMS Elements							
Element	Element Description	Total	Units	State 1	State 2	State 3	State 4
12	Concrete Deck	11040	SF	11012	28	0	0
13	Bridge Deck Surface	1100	SF	1081	18	1	0
35	Concrete Deck Soffit	11040	SF	11036	1	3	0
113	Steel Stringer	3864	LF	3853	0	11	0
114	Concrete Multiple Web Girder Unit	220	LF	218	0	2	0
126	Steel Thru Truss	1200	LF	1000	20	180	0
133	Truss Gusset Plates	112	EA	109	0	3	0
152	Steel Floor Beam	525	LF	523	0	2	0
162	Steel Pin	8	EA	8	0	0	0
200	Abutment Fill	2	EA	2	0	0	0
210	Concrete Pier Wall	40	LF	40	0	0	0
214	Concrete Web Wall between Columns	40	LF	40	0	0	0
215	Concrete Abutment	56	LF	56	0	0	0
227	Concrete Submerged Pile/Column	4	EA	4	0	0	0

BRIDGE INSPECTION REPORT

Status: Work
 CD Guid: 089e8183-e033-44d8-a7f8-30898ae839c1

Printed On: 4/26/2022
 Release Date:

Agency: Skagit County
 Program Mgr: Sonia L. Lowry

Br. No. 40070	SID 08228800	Br. Name SKAGIT RIVER MARBLEMOUNT
Carrying CASCADE RIVER RD		Route On 97950 Mile Post 0.03
Intersecting SKAGIT RIVER		Route Under Mile Post

BMS Elements (Continued)							
Element	Element Description	Total	Units	State 1	State 2	State 3	State 4
234	Concrete Pier Cap/Crossbeam	88	LF	88	0	0	0
311	Moveable Bearing (roller, sliding, etc)	14	EA	10	0	4	0
313	Fixed Bearing	10	EA	7	0	3	0
322	Approach Roadway Impact	2	EA	1	0	1	0
330	Metal Bridge Railing	1324	LF	1324	0	0	0
331	Concrete Bridge Railing	124	LF	59	0	65	0
355	Damaged Bolts or Rivets	18	EA	0	4	14	0
357	Pack Rust	7	EA	7	0	0	0
361	Scour	2	EA	0	2	0	0
400	Asphalt Butt Joint Seal	40	LF	0	0	40	0
402	Open Concrete Joint	580	LF	240	140	200	0
408	Steel Sliding Plate	40	LF	20	0	20	0
904	Organic Zinc/Urethane Paint System	100000	SF	78000	0	20000	2000

Notes	
0	Bridge is oriented west to east with the west end closest to Marblemount.
11	The load rating update calls for posting of all legal loads (see Summary Sheet1 in Records/Load Rating tab). Rather than posting load restrictions, traffic modifications have been made to restrict the bridge to a 1-lane, 2-way operation. This allows for legal loads to cross one at a time while traveling in the center of the bridge (see Summary Sheet2 in the Records/Load Rating tab). Field 1293 has been coded R.
12	Concrete deck (located in the main spans) has medium scaling with mud ball voids. Panel 1 has a 1 ft. x 3 ft. patch in the eastbound lane and a 6" diameter patch in the westbound lane. Panel 3 has two 6" diameter patches. Panel 4 has four patches for 4 sq. ft. total in the westbound lane along the centerline. Panel 5 has an 18" diameter patch in the westbound lane. Panel 8 has a 6" diameter patch in the westbound lane. Panel 11 has an 8" x 12" patch in the westbound lane near Panel Point 11. Panel 13 has a 1 sq. ft. patch in eastbound lane. Panel Point 13 south curb has a 6" x 6" x 2" deep spall. Panel 17 has two 6" diameter patches in the westbound lane. Panel 18 has a 9" x 4" patch in the eastbound lane. Panel 20 has a 6" diameter patch in the eastbound lane. Panel 23 has a 3 sq. ft. patch in eastbound lane. Panel 24 has a 10" diameter patch in the eastbound lane and a 4" diameter patch in the westbound lane. Panel 27 has 3 ft. x 6", and 6" x 6" patches in the westbound lane and a 10" diameter patch in the eastbound lane. Panel 30 has a 10" diameter patch and a 12" diameter patch in the westbound lane.
13	Deck surface over the approach spans is worn in the wheel lines. Span 1 has a 5 ft. x 20" patch near midspan and a 6" x 12" spall near Pier 2. See photos #37 and #38. REPAIR #12708. Span 5 has an 8 sq. ft. patch in the eastbound lane.
35	Soffit has a few transverse hairline cracks scattered throughout with some rust staining, and several areas of shallow delamination and spalling at the floor beams exposing rusty flanges. See photo #5 (typical). Panel 5, between Stringers A and B, there is a 1 ft. diameter patch and a 16" diameter spall around patch near Floorbeam 5. Panel 7, near Floor Beam 7, there is a spall 6" x 10" x 3" deep between Stringers E and F. Panel 18, there are rock pockets with exposed rebar between Stringers C and D.

BRIDGE INSPECTION REPORT

Status: Work
 CD Guid: 089e8183-e033-44d8-a7f8-30898ae839c1

Printed On: 4/26/2022
 Release Date:

Agency: Skagit County
 Program Mgr: Sonia L. Lowry

Br. No. 40070	SID 08228800	Br. Name SKAGIT RIVER MARBLEMOUNT
Carrying CASCADE RIVER RD		Route On 97950 Mile Post 0.03
Intersecting SKAGIT RIVER		Route Under Mile Post

Notes (Continued)

- | | |
|-----|--|
| 113 | <p>Steel stringers have scattered small rust blooms on flange edges of the exterior stringers and pack rust up to 1/4" in several of the erection angle seats.
 Stringer 10G top flange (at Floorbeam 9) and Stringer 11G top flange (at Floorbeam 10) each have a 6" diameter rust scallop. REPAIR #12714.
 Stringer 13G bottom flange (at Floorbeam 13) has laminar rust with approximately 10% section loss at erection angle seat. See photo #44. REPAIR #12714.
 Stringer 14G bottom flange (at Floorbeam 13) and Stringer 15G bottom flange (at Floorbeam 14) each are bent up 1" over a 12" length near the floorbeam connections.
 Stringer 24G bottom flange (near Floorbeam 23) has laminar rust over 12" with approximately 10% section loss. See photo #45. REPAIR #12714.
 Stringer 28C bottom flange near Floorbeam 28, is bent upward 1".</p> |
| 114 | <p>Concrete multiweb girders, in Spans 1 and 5, have vertical hairline cracks in the webs and water leakage between the girder segments.
 Girder 5B north web over Bearing 5C has a 16" x 2" x 3" delamination.</p> |
| 126 | <p>Steel thru truss, at the end posts, is reinforced by 6" x 3/4" plates welded on both sides of each channel.
 Both trusses have minor traffic impact damage present in a few vertical members.</p> <p>Bottom chords of both north and south trusses have a few areas of debris that inhibits inspection (areas are primarily over land at ends of truss spans). See photos #42 and #43. REPAIR #12711.</p> <p>See "Visual Fracture Critical Report" attached to the files tab for more information.</p> |
| 133 | <p>Gusset plates with misdrilled holes, broken or missing rivets, and minor corrosion are detailed in the "Visual Fracture Critical Report" attached to the files tab.</p> |
| 152 | <p>Steel floor beams have top flange rust in several locations and minor section loss with shallow pitting.
 Floor Beam 1, below Stringer 1G at the west face, has an 8" x 6" area of pitting up to 1/16" deep.
 Floor Beam 28, the bottom flange is gouged and bent 3/4" over a 12" length from a high load hit. See photo #4.</p> |
| 162 | <p>Steel pins are in the top chords.
 All pins have minor rust blooms and pitting. Pins were UT'd in 2020 with no indications noted. See the "UT Inspection Report." For additional specific information and call outs, see "Visual Fracture Critical Report" and the "Pin Inspection Schedule and Summary Sheet."</p> |
| 210 | <p>Concrete pier walls are located at Piers 2 and 5.</p> |
| 214 | <p>Web walls, at Piers 3 and 4, have vertical and diagonal hairline cracks and are abraded at the water line.</p> |
| 215 | <p>Concrete abutments have sloughing approach fills with erosion voids up to 10" high over most of their length.</p> |
| 227 | <p>Concrete submerged Columns at Piers 3 and 4, have vertical hairline leaching cracks in the top.</p> |
| 234 | <p>Concrete pier caps have a few vertical hairline leaching cracks and small shallow popouts scattered throughout.</p> |
| 311 | <p>Rocker bearings for concrete girder units are at Pier 2 and Pier 5.
 In several locations lock nuts at the masonry plates have laminar rust blossoms with up to 1/16" section loss, most notable at Bearings 2A and 2C.
 Truss span Bearing 2A is missing a nut at the southwest corner for the masonry plate and has a loose nut at the southeast corner. See photo #33. REPAIR #12715.</p> |
| 313 | <p>Fixed Bearings are at Piers 1, 3 and 6. The deficiencies listed below have been painted over and have existed for a while without any detrimental affects.
 Bearing 1A has a loose nut at the bottom SE corner.
 Bearing 1C has a missing nut the top SE corner. See photo #34 (typical).
 Bearing 1D has a missing nut at the top NE corner and bottom NW corner.</p> |
| 322 | <p>East approach has approximately 1/2" of settlement.</p> |

BRIDGE INSPECTION REPORT

Status: Work
 CD Guid: 089e8183-e033-44d8-a7f8-30898ae839c1

Printed On: 4/26/2022
 Release Date:

Agency: Skagit County
 Program Mgr: Sonia L. Lowry

Br. No. 40070	SID 08228800	Br. Name SKAGIT RIVER MARBLEMOUNT
Carrying CASCADE RIVER RD		Route On 97950 Mile Post 0.03
Intersecting SKAGIT RIVER		Route Under Mile Post

Notes (Continued)

- 330 Metal bridge rail consists of thrie-beam rail retrofitted to the original concrete baluster rail.
- 331 Concrete bridge rails over the approach spans are covered with moss. The top rails are cracked, exfoliated and spalled up to 3" deep. The posts are cracked and delaminating. The heaviest deterioration is in the north rails. See photo #36.
- 355 Damaged, broken and missing rivets are present in the truss members. See element 126.
- 357 Pack rust in stringers. See element 113.
- 361 Skagit River flows north to south below Spans 2, 3 and 4. Tops of footings at Piers 3 and 4 have been exposed in the past. Pier 4 is beginning to re-accumulate debris. See photo #41. REPAIR #12705.
- 400 Asphalt butt joints at abutments are not sawcut and sealed. East abutment joint has approximately 4 ft. of total patches and a 2 ft. x 8" x 1" deep pothole in the eastbound lane. See photo #46. REPAIR #12712.
- 402 Open concrete joints over the truss panel points have poured rubber filler. Panel Point 1 has a 6 ft. x 9" patch in the westbound lane and centerline. Panel Point 2 has 2 ft. x 10" patch in the westbound lane and 10" x 6" patch in the eastbound lane. Panel Point 3 has an 18 ft. patch up to 24" wide. Panel Point 4 is patched full width. Panel Point 5 is patched full width. Panel Point 6 has an 9 ft. x 24" patch in the westbound lane and a 24" x 12" patch in the eastbound lane. Panel Point 7 has a 10 ft. x up to 18" patch in the eastbound lane. Panel Point 9 has a 4 ft. x 6" patch in the eastbound lane. Panel Point 11 has a 24" x 6" patch in the westbound lane. Panel Point 13 has a 4 ft. x 6" patch in westbound and a 6 ft. x 12" patch in the eastbound lane. Panel Point 16 has a 4 ft. x 9" patch in the westbound lane and a 4 ft. x 1 ft. patch in the eastbound lane. Panel Point 17 has a 2 ft. x 6" patch in the westbound lane. Panel Point 19 has a 2 sq. ft. patch in the eastbound lane. Panel Point 20 has a 4 ft. x 18" patch at the centerline. Panel Point 23 has a 6 ft. x 9" patch at the centerline and eastbound lane. Panel Point 24 has a 3 ft. x 12" patch in the eastbound lane. Panel Point 25 has a 6 ft. x 12" patch in the westbound lane.
- 408 Steel sliding plate joints are full of debris. West joint has a 6" crack in the east steel header at centerline. See photo #47.

 Joints are measured just north of centerline (due to west joint offset at centerline). See photo #47.

Year	West Joint	East Joint	Temp (F)	Time
2020	1-1/2"	1-1/2"	40 °	11:00
2018	1-1/2"	1-7/8"	40 °	11:00
2016	1-1/2"	1-5/8"	47 °	10:00
- 904 Paint system is chalky with wide spread cracking, areas of heavy peeling and exposed primer. There is rust staining in some locations that is associated with areas of cracked and bubbled paint that is exposing metal substrate, heaviest on the south face of members. See photos #28 and #29.
- 1660 Rating factor of 0.61 for AASHTO 3, therefore, coding set at 1
- 1677 Channel banks are well vegetated upstream and downstream with some sloughing. See photos #39 and #40.
- 1680 Piers are supported by timber piles.
- 1685 Northeast transition has minor impact damage and a split spacer block. See photo #19. REPAIR #12703.
- 1686 Guardrail has minor traffic damage at the southwest corner. Northwest guardrail has traffic impact over a 20 ft. length. See photo #35. REPAIR #12707.

BRIDGE INSPECTION REPORT

Status: Work
 CD Guid: 089e8183-e033-44d8-a7f8-30898ae839c1

Printed On: 4/26/2022
 Release Date:

Agency: Skagit County
 Program Mgr: Sonia L. Lowry

Br. No. 40070	SID 08228800	Br. Name SKAGIT RIVER MARBLEMOUNT
Carrying CASCADE RIVER RD		Route On 97950 Mile Post 0.03
Intersecting SKAGIT RIVER		Route Under Mile Post

Notes (Continued)

7664 Drains are open and working properly.

Repairs

Repair No	Pr	R	Repair Descriptions	Noted	Maint	Verified
12703	0	J	Replace split spacer block at northeast corner.	3/17/2010		
12705	1	B	Remove debris from upstream face of Pier 4. (This is a recurrent problem, consider the installation of a shark or debris deflector).	3/14/2012		
12707	1	J	Repair or replace the 20 ft. length of damaged guardrail at the northwest corner.	3/25/2014		
12708	1	B	Remove loose or spalled concrete from the spalled deck surface over Span 1. Clean and paint any exposed rebar and patch with an approved material.	3/25/2014		
12711	1	B	Bottom chords of both north and south trusses have a few areas of debris that inhibits inspection (areas are primarily over land at ends of truss spans). Clean debris from bottom chords prior to next scheduled UBIT inspection in 3/2022 (majority of debris can be seen and maybe accessed from deck).	3/4/2020		
12712	1	J	Remove loose ACP and patch pothole at east abument joint in the eastbound lane.	3/4/2020		
12714	2	B	Remove rust, apply rust inhibitor and touch-up paint the stringers at the following locations: Stringer 10G top flange (at Floorbeam 9). Stringer 11G top flange (at Floorbeam 10). Stringer 13G bottom flange (at Floorbeam 13) at erection angle seat. Stringer 24G bottom flange (near Floorbeam 23).	3/4/2020		
12715	2	B	Replace missing nut at Truss span Bearing 2A at the southwest corner for the masonry plate and tighten loose nut at the southeast corner.	3/4/2020		
12716	1	J	Install signage for Load Restrictions	10/13/2020		

Inspections Performed and Resources Required

Report Type	Date	Freq	Hrs	Insp	CertNo	Coinsp	Note
Routine	3/22/2022	24	1.0	TKK	G1303	PFK	
Resources	Hours	Min	Pref	Max	Freq Date	Need Date	Override Notes
SNDG					72 3/4/2020	3/4/2026	CAUTION: Watch out for boats!
Fracture Critical	3/22/2022	24	12.0	TKK	G1303	PFK	Extra time needed due to using UB-30 (see UBIT resource below).
Resources	Hours	Min	Pref	Max	Freq Date	Need Date	Override Notes

BRIDGE INSPECTION REPORT

Status: Work
 CD Guid: 089e8183-e033-44d8-a7f8-30898ae839c1

Printed On: 4/26/2022
 Release Date:

Agency: Skagit County
 Program Mgr: Sonia L. Lowry

Br. No. 40070	SID 08228800	Br. Name SKAGIT RIVER MARBLEMOUNT
Carrying CASCADE RIVER RD		Route On 97950 Mile Post 0.03
Intersecting SKAGIT RIVER		Route Under Mile Post

Inspections Performed and Resources Required (Continued)

Report Type	Date	Freq	Hrs	Insp	CertNo	Coinsp	Note
UBIT	9.00	30	30	30	24	3/22/2022 3/22/2024	<p>Unable to deploy off north side due to power lines.</p> <p>UB-30 used in 2020 and 2022 due to load rating values being well below weight of UB-52 and UB-62 (Load Rating had not been done since 1985 and values in Load Rating tab were updated prior to 2020 inspection to match/reflect 1985 Load Rating). It was decided to be safe, to use UB-30. Re-evaluate next inspection if a current load rating has been completed and if UB-52 or UB-62 would work.</p> <p>Note: UB-30 requires deploying through truss within every other panel at minimum (deployment through every panel would be ideal if time permits).</p>
Bucket	3.00	BK	BK	BK	24	3/22/2022 3/22/2024	<p>In 2022, Skagit County bucket truck was used to inspect upper members of both trusses. Used their large "Forestry" bucket truck and it worked well (despite its size).</p>
Flagging	13.00	LA	LA	LA			<p>Contact Skagit County for scheduling inspections and traffic control: Torey Nelson = (360) 416-1425 / toreyn@co.skagit.wa.us Forrest Jones = (360) 416-1400 / forrestj@co.skagit.wa.us</p>
Special Equipment	2.00	UT	UT	UT			<p>UT eight pins total in top chord of both trusses on a 72 month frequency (use 2.25Mhz/0.75 transducer). See 'Pin Inspection Schedule' for details. Last completed in 2020. Next due in 2026.</p>

BRIDGE INSPECTION REPORT

Status: Work
CD Guid: 089e8183-e033-44d8-a7f8-30898ae839c1

Printed On: 4/26/2022
Release Date:

Agency: Skagit County
Program Mgr: Sonia L. Lowry

Br. No. 40070
Carrying CASCADE RIVER RD
Intersecting SKAGIT RIVER

SID 08228800

Br. Name SKAGIT RIVER MARBLEMOUNT
Route On 97950 **Mile Post** 0.03
Route Under **Mile Post**

SI-25

0 Orientation
Photo Type: D - Deck
Orientation: E
Date: 3/25/2014
Repairs:
Deck looking east.



SI-26

0 Orientation
Photo Type: E - Elevation
Orientation: NW
Date: 3/25/2014
Repairs:
Elevation looking northwest.



BRIDGE INSPECTION REPORT

Status: Work
CD Guid: 089e8183-e033-44d8-a7f8-30898ae839c1

Printed On: 4/26/2022
Release Date:

Agency: Skagit County
Program Mgr: Sonia L. Lowry

Br. No. 40070
Carrying CASCADE RIVER RD
Intersecting SKAGIT RIVER

SID 08228800

Br. Name SKAGIT RIVER MARBLEMOUNT
Route On 97950 **Mile Post** 0.03
Route Under **Mile Post**

SI-48

Traffic Revision
Photo Type: C - Completed
Orientation: W
Date: 10/13/2020
Repairs:
Traffic Revision - 1 Lane, 2-Way



SI-49

Traffic Revision
Photo Type: C - Completed
Orientation: E
Date: 10/13/2020
Repairs:
Traffic Revision - 1 Lane, 2-Way



BRIDGE INSPECTION REPORT

Status: Work
CD Guid: 089e8183-e033-44d8-a7f8-30898ae839c1

Printed On: 4/26/2022
Release Date:

Agency: Skagit County
Program Mgr: Sonia L. Lowry

Br. No. 40070
Carrying CASCADE RIVER RD
Intersecting SKAGIT RIVER

SID 08228800

Br. Name SKAGIT RIVER MARBLEMOUNT
Route On 97950 **Mile Post** 0.03
Route Under **Mile Post**

SI-50

Traffic Revision
Photo Type: C - Completed
Orientation: E
Date: 10/13/2020
Repairs:
Traffic Revision - 1 Lane, 2-Way



SI-51

Traffic Revision
Photo Type: C - Completed
Orientation: E
Date: 10/13/2020
Repairs:
Traffic Revision - 1 Lane, 2-Way



BRIDGE INSPECTION REPORT

Status: Work
CD Guid: 089e8183-e033-44d8-a7f8-30898ae839c1

Printed On: 4/26/2022
Release Date:

Agency: Skagit County
Program Mgr: Sonia L. Lowry

Br. No. 40070
Carrying CASCADE RIVER RD
Intersecting SKAGIT RIVER

SID 08228800

Br. Name SKAGIT RIVER MARBLEMOUNT

Route On 97950 **Mile Post** 0.03
Route Under **Mile Post**

SI-37

13 Bridge Deck Surface
Photo Type: G - General
Orientation: SE
Date: 3/25/2014
Repairs:
Span 1 has a 5 ft. patch at the centerline.



SI-38

13 Bridge Deck Surface
Photo Type: R - Repair
Orientation: S
Date: 3/25/2014
Repairs: 12708
Span 1 spall near Pier 2.



BRIDGE INSPECTION REPORT

Status: Work
CD Guid: 089e8183-e033-44d8-a7f8-30898ae839c1

Printed On: 4/26/2022
Release Date:

Agency: Skagit County
Program Mgr: Sonia L. Lowry

Br. No. 40070	SID 08228800	Br. Name SKAGIT RIVER MARBLEMOUNT
Carrying CASCADE RIVER RD	Route On 97950	Mile Post 0.03
Intersecting SKAGIT RIVER	Route Under	Mile Post

SI-5

35 Soffit
 Photo Type: G - General
 Orientation: UP
 Date: 4/17/2002
 Repairs:
 Span 3 Floorbeam 16 corrosion between Stringers E and F.



SI-44

113 Steel Stringer
 Photo Type: G - General
 Orientation: SE
 Date: 3/4/2020
 Repairs: 12714
 Stringer 13G bottom flange (at Floorbeam 13) has laminar rust at erection angle seat.



BRIDGE INSPECTION REPORT

Status: Work
CD Guid: 089e8183-e033-44d8-a7f8-30898ae839c1

Printed On: 4/26/2022
Release Date:

Agency: Skagit County
Program Mgr: Sonia L. Lowry

Br. No. 40070
Carrying CASCADE RIVER RD
Intersecting SKAGIT RIVER

SID 08228800

Br. Name SKAGIT RIVER MARBLEMOUNT
Route On 97950 **Mile Post** 0.03
Route Under **Mile Post**

SI-45

113 Steel Stringer

Photo Type: G - General

Orientation: NW

Date: 3/4/2020

Repairs: 12714

Stringer 24G bottom flange (near Floorbeam 23) has laminar rust.



SI-42

126 Steel Thru Truss

Photo Type: R - Repair

Orientation: W

Date: 3/4/2020

Repairs: 12711

Debris on bottom chord at L26 to L27 south truss at panel point L26S.



BRIDGE INSPECTION REPORT

Status: Work
CD Guid: 089e8183-e033-44d8-a7f8-30898ae839c1

Printed On: 4/26/2022
Release Date:

Agency: Skagit County
Program Mgr: Sonia L. Lowry

Br. No. 40070
Carrying CASCADE RIVER RD
Intersecting SKAGIT RIVER

SID 08228800

Br. Name SKAGIT RIVER MARBLEMOUNT
Route On 97950 **Mile Post** 0.03
Route Under **Mile Post**

SI-43

126 Steel Thru Truss
Photo Type: R - Repair
Orientation: DN
Date: 3/4/2020
Repairs: 12711
Debris on bottom chord at L25 to L26
south truss at panel point L26S.



SI-30

126 Steel Thru Truss
Photo Type: G - General
Orientation: E
Date: 3/25/2014
Repairs:
L20 South bottom edge of interior gusset plate is corroded to a knife edge.



BRIDGE INSPECTION REPORT

Status: Work
CD Guid: 089e8183-e033-44d8-a7f8-30898ae839c1

Printed On: 4/26/2022
Release Date:

Agency: Skagit County
Program Mgr: Sonia L. Lowry

Br. No. 40070	SID 08228800	Br. Name SKAGIT RIVER MARBLEMOUNT	Route On 97950	Mile Post 0.03
Carrying CASCADE RIVER RD			Route Under	Mile Post
Intersecting SKAGIT RIVER				

MI-4

152 Steel Floorbeam
Photo Type: G - General
Orientation: E
Date: 4/17/2002
Repairs:
Damaged Floorbeam 28.



SI-33

311 Moveable Bearing (roller, sliding, etc)
Photo Type: G - General
Orientation: NW
Date: 3/25/2014
Repairs: 12715
Bearing 2A for the truss span has a missing nut at the SW corner and the nut is not engaged at the SE corner.



BRIDGE INSPECTION REPORT

Status: Work
CD Guid: 089e8183-e033-44d8-a7f8-30898ae839c1

Printed On: 4/26/2022
Release Date:

Agency: Skagit County
Program Mgr: Sonia L. Lowry

Br. No. 40070
Carrying CASCADE RIVER RD
Intersecting SKAGIT RIVER

SID 08228800

Br. Name SKAGIT RIVER MARBLEMOUNT

Route On 97950 **Mile Post** 0.03
Route Under **Mile Post**

SI-34

313 Fixed Bearing
Photo Type: G - General
Orientation: NW
Date: 3/25/2014
Repairs:
Bearing 1C is missing a nut at the top southeast corner.



SI-36

331 Concrete Bridge Railing
Photo Type: G - General
Orientation: N
Date: 3/25/2014
Repairs:
Concrete bridge rails are cracked, exfoliated and spalled in areas. Northwest rail is shown.



BRIDGE INSPECTION REPORT

Status: Work
CD Guid: 089e8183-e033-44d8-a7f8-30898ae839c1

Printed On: 4/26/2022
Release Date:

Agency: Skagit County
Program Mgr: Sonia L. Lowry

Br. No. 40070
Carrying CASCADE RIVER RD
Intersecting SKAGIT RIVER

SID 08228800

Br. Name SKAGIT RIVER MARBLEMOUNT

Route On 97950 **Mile Post** 0.03
Route Under **Mile Post**

SI-41

361 Scour
Photo Type: R - Repair
Orientation: E
Date: 3/4/2020
Repairs: 12705
Pier 4 upstream nose is accumulating debris.



SI-46

400 Asphalt Butt Joint Seal
Photo Type: J - Reg Road Maint
Orientation: E
Date: 3/4/2020
Repairs: 12712
East abutment joint has a pothole in the eastbound lane.



BRIDGE INSPECTION REPORT

Status: Work
CD Guid: 089e8183-e033-44d8-a7f8-30898ae839c1

Printed On: 4/26/2022
Release Date:

Agency: Skagit County
Program Mgr: Sonia L. Lowry

Br. No. 40070
Carrying CASCADE RIVER RD
Intersecting SKAGIT RIVER

SID 08228800

Br. Name SKAGIT RIVER MARBLEMOUNT
Route On 97950 **Mile Post** 0.03
Route Under **Mile Post**

SI-47

408 Steel Sliding Plate
Photo Type: G - General
Orientation: N
Date: 3/4/2020
Repairs:
West joint has a 6" crack in the east steel header at centerline. Note: offset of joint at centerline for joint measurements.



SI-29

904 Paint
Photo Type: G - General
Orientation: N
Date: 3/25/2014
Repairs:
Wide spread paint cracking with heavy rust staining.



BRIDGE INSPECTION REPORT

Status: Work

Printed On: 4/26/2022

Agency: Skagit County

CD Guid: 089e8183-e033-44d8-a7f8-30898ae839c1

Release Date:

Program Mgr: Sonia L. Lowry

Br. No. 40070

SID 08228800

Br. Name SKAGIT RIVER MARBLEMOUNT

Carrying CASCADE RIVER RD

Route On 97950

Mile Post 0.03

Intersecting SKAGIT RIVER

Route Under

Mile Post

SI-28

904 Paint

Photo Type: G - General

Orientation: N

Date: 3/25/2014

Repairs:

Peeling paint with surface rust and wide spread rust staining.



SI-39

1677 Channel Protection

Photo Type: S - Scour

Orientation: N

Date: 3/4/2020

Repairs:

Upstream channel.



BRIDGE INSPECTION REPORT

Status: Work
CD Guid: 089e8183-e033-44d8-a7f8-30898ae839c1

Printed On: 4/26/2022
Release Date:

Agency: Skagit County
Program Mgr: Sonia L. Lowry

Br. No. 40070
Carrying CASCADE RIVER RD
Intersecting SKAGIT RIVER

SID 08228800

Br. Name SKAGIT RIVER MARBLEMOUNT

Route On 97950 **Mile Post** 0.03
Route Under **Mile Post**

SI-40

1677 Channel Protection
Photo Type: S - Scour
Orientation: S
Date: 3/4/2020
Repairs:
Downstream channel.



SI-19

1685 Transitions
Photo Type: J - Reg Road Maint
Orientation: E
Date: 3/17/2010
Repairs: 12703
Split spacer block at northeast corner.



BRIDGE INSPECTION REPORT

Status: Work
CD Guid: 089e8183-e033-44d8-a7f8-30898ae839c1

Printed On: 4/26/2022
Release Date:

Agency: Skagit County
Program Mgr: Sonia L. Lowry

Br. No. 40070
Carrying CASCADE RIVER RD
Intersecting SKAGIT RIVER

SID 08228800

Br. Name SKAGIT RIVER MARBLEMOUNT
Route On 97950 **Mile Post** 0.03
Route Under **Mile Post**

SI-35

1686 Guardrails

Photo Type: J - Reg Road Maint

Orientation: W

Date: 3/25/2014

Repairs: 12707

Guardrail at the northwest corner has traffic impact damage over a 20 ft.



BRIDGE INSPECTION REPORT

Status: Work
 CD Guid: 089e8183-e033-44d8-a7f8-30898ae839c1

Printed On: 4/26/2022
 Release Date:

Agency: Skagit County
 Program Mgr: Sonia L. Lowry

Br. No. 40070	SID 08228800	Br. Name SKAGIT RIVER MARBLEMOUNT
Carrying CASCADE RIVER RD		Route On 97950 Mile Post 0.03
Intersecting SKAGIT RIVER		Route Under Mile Post

Entry Name	Folder Name	Type	Repairs	Page
SI-25	0 Orientation	D		1
SI-26	0 Orientation	E		1
SI-48	Traffic Revision	C		2
SI-49	Traffic Revision	C		2
SI-50	Traffic Revision	C		3
SI-51	Traffic Revision	C		3
SI-37	13 Bridge Deck Surface	G		4
SI-38	13 Bridge Deck Surface	R	12708	4
SI-5	35 Soffit	G		5
SI-44	113 Steel Stringer	G	12714	5
SI-45	113 Steel Stringer	G	12714	6
SI-42	126 Steel Thru Truss	R	12711	6
SI-43	126 Steel Thru Truss	R	12711	7
SI-30	126 Steel Thru Truss	G		7
MI-4	152 Steel Floorbeam	G		8
SI-33	311 Moveable Bearing (roller, sliding, etc)	G	12715	8
SI-34	313 Fixed Bearing	G		9
SI-36	331 Concrete Bridge Railing	G		9
SI-41	361 Scour	R	12705	10
SI-46	400 Asphalt Butt Joint Seal	J	12712	10
SI-47	408 Steel Sliding Plate	G		11
SI-29	904 Paint	G		11
SI-28	904 Paint	G		12
SI-39	1677 Channel Protection	S		12
SI-40	1677 Channel Protection	S		13
SI-19	1685 Transitions	J	12703	13
SI-35	1686 Guardrails	J	12707	14

Bridge ID	1001	2009	2132	1019	1286	1021	2023	1156	2181	2183	2185	1188	1196
Structure ID	Bridge Number	Bridge Name	Owner	Count	County	City	Location	Section	Township	Range	Latitude	Longitude	
08228800	40070	SKAGIT RIVER MARBLEMOUNT	02	02	29	0000	0.03 E JCT SR 20	18	35	11E	48° 31' 36.00"	121° 25' 48.00"	

Facilities	1232	1256	1274	7281	7283	1276	1285	1288	1289	1293	1292	2295	7296	Printed Date	Sufficiency Rating	Status	Routine Risk Category	Underwater Risk Category
Feature Intersected	Facilities Carried	Region	Leg1	Leg2	FIPS	Tol	Para	Temp	OpC	NRHP	HAER	LHP	Printed Date	Sufficiency Rating	Status	Routine Risk Category	Underwater Risk Category	
SKAGIT RIVER	CASCADE RIVER RD	NW	39	0	99057	3	N		R	5			4/26/2022	32.38	SD	High Risk		

Layout	1332	1336	1340	2346	1348	1352	1356	1360	1364	1367	1310	1312	1370	1374	1378	1379	1382	1383	1386	1387	1390	1394	1291	1397
Year Built	Year Rebuilt	Bridge Length	Screening Length	Maximum Span Length	Lanes On	Curb to Curb Deck Width	Out to Out Deck Width	Sidewalk Left	Sidewalk Right	Skew	Flared	Min Vert Over Deck	Min Vert Under	Vert Code	Min Lat Under Right	Lat Code	Min Lat Under Left	Nav Vert Clear	Nav Horiz Clear	Nav Vert Lift Clear	Median	Appr Rdwy		
1930	0	662		280	1	14.0	22.0	0.0	0.0	0	N	17° 09"	00° 00"	N	0.0	N	0.0	0	0	0	0	0	20	

Crossing	1432	1433	1434	1435	2440	1445	1451	1453	1457	1463	1467	2410	7479	1483	1484	1485	1486	1487	1489	1490	1354	1491	1495	1499	1413	2441
On/Under	HW Class	Service Level	Route Number	Milepost	ADT	Truck %	Year of ADT	Future ADT	Future ADT Year	Linear Referencing System	NBI	Fed Aid Route #	NHS	BHS	STRAH	ELH	Funct. Class	NTN	Lane Use Direction	Lanes Under	Horizontal Clearance Route Dir	Horizontal Clearance Reverse Dir	Max Vert Clearance Route	Detour	Speed Limit	
1	4	1	97950	0.03	608	11	2020	742	2040		Y	0000	0	0	0	2	08	N	5	0	20° 00"		17° 09"	20	25	

Design	1532	1533	1535	1536	1538	1541	1544	1545	1546	1547	1548	1549	1550	1551	1552	1553	1554	1555	1556	1585	1588	1590	7565	7557
Main Span Material	Main Span Design	Appr Span Material	Appr Span Design	Number Main Spans	Number Appr Spans	Service On	Service Under	Deck Type	Wearing Surface	Membrane	Deck Protect	Design Load Code	Oper Rating Method	Oper Rating Tons	Oper Rating Factor	Inv Rating Method	Inv Rating Tons	Inv Rating Factor	Border Risk State Cd	Border	Border Structure ID	Fed Aid Project No	Design Exemption	
3	10	1	22	3	2	1	5	1	1	0	0	2	3	12	0.32	3	8	0.22						

Load Rating	2587	2588	2589	2590	2591	2592	2593	2594	2597	2598	2595	2596	7832	7833	7834	7835	7836	7837	7838	7839	7840	7841	1844	1846	1847	2853	2860	1867	1873	2870	1861	1879	2883
Type 3	Type 3S2	Type 3-3	NRL	SHV 4	SHV 5	SHV 6	SHV 7	EV 2	EV 3	OL 1	OL 2	Water	Flood Ppt Int	Flood Control	Struct Risk	Strutted	Strutted	Strutted	Windy	Seismic	Seismic	Seismic	Paris In Vals	Work Meas	Stru Imp Length	Roadway Width	Cost Per SF	Struct Cost	Rdwy Cost	Engr Cost	Total Cost	Estmt Year	Prop Inst Cost Code
0.95	0.69	0.61	0.60	0.87	0.76	0.69	0.62	0.82	0.55	0.70	0.36	F	C	U	C	3	4	A	D	N	2	31	1	672	26	800	6989	1398	5591	13978	2014	Y	

Inspection Report Types	2920	1990	2646	2649	2654
Inspection	Date	Inspector	Cert No	Co-Inspector	
Routine	3/22/2022	TKK	G1303	PFK	
Fracture Critical	3/22/2022	TKK	G1303	PFK	
Special Feature					
Underwater					
UW Interim					

Inspection	Date	Inspector	Cert No	Co-Inspector
Interim				
In Depth				
Damage				
PRM Safety				
SEC Safety				

Inspection	Date	Inspector	Cert No	Co-Inspector
Condition				
Short Span				
Geometric				
Info				
Inventory				



Skagit County Public Works

Appendix C – Bridge Load Rating

BRIDGE RATING SUMMARY

Bridge Name: SKAGIT RIVER MARBLEMOUNT
 Bridge Number: 40070
 SID Number: 08228800
 Span Types: Continuous Steel Truss
 Bridge Length: 662-feet
 Design Load: 20 Ton Truck
 Rated By: Arzhang Alimoradi
 Checked By: Pai-hsin Wu
 Date: 9/29/2020



EXPIRES 5/18/2021

Inspection Report Date	3/26/2018	Superstructure Condition	6
Overlay Thickness	0.0"	Substructure Condition	7
Rating Method	LRFR	Deck Condition	6

Truck	RF (INV)	RF (OPR)	Controlling Point
AASHTO-1	<u>0.57</u>	<u>0.95</u>	<u>Gusset Plate L10 Connecting to U11</u>
AASHTO-2	<u>0.41</u>	<u>0.69</u>	<u>Gusset Plate L10 Connecting to U11</u>
AASHTO-3	<u>0.37</u>	<u>0.61</u>	<u>Gusset Plate L10 Connecting to U11</u>
NRL	<u>0.36</u>	<u>0.60</u>	<u>Gusset Plate L10 Connecting to U11</u>
EV2	<u>0.49</u>	<u>0.82</u>	<u>Gusset Plate L10 Connecting to U11</u>
EV3	<u>0.33</u>	<u>0.55</u>	<u>Gusset Plate L10 Connecting to U11</u>
OL-1	<u>0.42</u>	<u>0.70</u>	<u>Gusset Plate L10 Connecting to U11</u>
OL-2	<u>0.22</u>	<u>0.36</u>	<u>Gusset Plate L10 Connecting to U11</u>

NBI Rating	RF	Ton (US)	Controlling Point
Inventory (HL-93)	<u>0.22</u>	<u>7.92</u>	<u>Gusset Plate L10 Connecting to U11</u>
Operating (HL-93)	<u>0.32</u>	<u>11.52</u>	<u>Gusset Plate L10 Connecting to U11</u>

SHV Rating	RF (OPR)	Ton (US)	Controlling Point
SU4 (GVW = 54K)	<u>0.87</u>	<u>23.49</u>	<u>Gusset Plate L10 Connecting to U11</u>
SU5 (GVW = 62K)	<u>0.76</u>	<u>23.56</u>	<u>Gusset Plate L10 Connecting to U11</u>
SU6 (GVW = 69.5K)	<u>0.69</u>	<u>23.98</u>	<u>Gusset Plate L10 Connecting to U11</u>
SU7 (GVW = 77.5K)	<u>0.62</u>	<u>24.03</u>	<u>Gusset Plate L10 Connecting to U11</u>

Remarks: This bridge needs to be posted for all legal AASHTO and SU trucks.



Skagit County Public Works

Appendix D – In-Depth Inspections

VISUAL FRACTURE CRITICAL INSPECTION REPORT

Bridge Name: SKAGIT RIVER MARBLEMOUNT	Date: 3/4/2020
Bridge No: 40070	Hours: 10.0
Structure ID: 08228800	Inspector ID #: G1303
Structure Type: STRUS PCMWG	Lead Inspector Initials: TKK
Agency: SKAGIT COUNTY	Co-Inspector Initials: WAW
Milepost: 0.03	

Lead Inspector Signature: _____

Inspected items: Truss Tension Members/Pins **Co-Inspector Signature:** _____

Procedures:

Riveted Truss

1. As required, use mirrors or other equipment to check inside surfaces of FCM's.
2. Check for loose or unevenly loaded member sub-elements.
3. Check all rivets at connection plates, with emphasis on first row. The first row is the row closest to the edge of the connection or gusset plate.
4. Check for any welds, including plug, tack, or repair welds. Record location of welds, regardless of condition, and document weld type and category.
5. Check FC members and associated connection or gusset plates for areas of heavy or pitted corrosion, nicks, gouges, sharp bends, and collision damage. Record location of all these conditions and estimated section loss, if applicable.
6. Check all heat straightened or repaired areas. Record location of these areas, regardless of condition.


Pins and Anchor Bolts

1. As required, use mirrors or other equipment to check inside surfaces of FCM's.
2. Check for pitting, laminar rust, surface deformation, and pack rust. It is important to check the pin, pin nuts, and all members surrounding the pin for this kind of steel deterioration.
3. Check for mobility and noise of pin and surrounding members. If the pin is physically "frozen" it is important to note this because the added stress can affect other members in the structure.
4. Observe and record abnormalities like; alignment, pin wear, loose pin nuts, and amount of nut engagement. It's important to note that full nut engagement is when the nut is flush with the pin or the pin is extending past the nut.
5. Check for paint system failure on pin nuts, pin, and surrounding members.

FCM Location	FCM Type	FCM Per Truss Line	BEIST Server Plans		
			Sh. No.	Contr.	Sh. Name
North and South Trusses	Tension Members	65			
	Pins				

Note: FCM = Fracture Critical Member

VISUAL FRACTURE CRITICAL INSPECTION REPORT



Truss Line	Span	Location	FC	Feature Inspected	Detail Description	Remarks
General Note: Truss member have heavy rust staining with areas of surface and seam rust (staining is heaviest on the south truss face). Many of the bottom lateral gusset plates have edge rust.						
South	2	L0-L1	Y	Bottom Chord	Built up angles w/ tie plates	No significant defects noted.
South	2	U1-L1	Y	Vertical	Double angles w/ tie plates	No significant defects noted.
South	2	U1-L2	Y	Diagonal	Built up angles w/ lattice web	No significant defects noted.
South	2	L1-L2	Y	Bottom Chord	Built up angles w/ tie plates	No significant defects noted.
South	2	L2-L3	Y	Bottom Chord	Built up angles w/ lattice web	No significant defects noted.
South	2	L2-U3	Y	Diagonal	Double channels w/ lattice web	No significant defects noted.
South	2	U3-L3	Y	Vertical	Double angles w/ lattice web	No significant defects noted.
South	2	U3-U4	Y	Top Chord	Channels w/ lattice web and tie plates	No significant defects noted.
South	2	U4-U5	Y	Top Chord	Channels w/ lattice web and tie plates	No significant defects noted.
South	2	L3-L4	Y	Bottom Chord	Built up angles w/ lattice web	No significant defects noted.
South	2	L4-U5	Y	Diagonal	Double channels w/ tie plates	No significant defects noted.
South	2	U5-L5	Y	Vertical	Double angles w/ lattice web	No significant defects noted.
South	2	L4-L5	Y	Bottom Chord	Double channels w/ lattice web	No significant defects noted.
South	2	L5-L6	Y	Bottom Chord	Double channels w/ lattice web	No significant defects noted.
South	2	L6-L7	N	Bottom Chord	Channels w/ lattice web and tie plates	Near L6, there is a missing rivet.
South	2	U5-U7	Y	Top Chord	Channels w/ lattice web and tie plates	No significant defects noted.

VISUAL FRACTURE CRITICAL INSPECTION REPORT

Truss Line	Span	Location	FC	Feature Inspected	Detail Description	Remarks
South	2	L6-U7	Y	Diagonal	Double channels w/ tie plates	No significant defects noted.
South	2	U7-L7	Y	Vertical	Double angles w/ lattice web	At L7 there are 3/4" and 1/2" mis-drilled holes in top of the gusset plate.
South	2	U7	Y	Pin	18-3/4" x 5-3/4" dia. Shldr 17"	Pin has minor surface rust blooms.
South	2/3	U7-U9	Y	TC Eyebar	Solid Bar Stock	At U9 there is minor surface rust around the pin.
South	3	U9	Y	Pin	18-3/4" x 5-3/4" dia. Shldr 17"	Pin has minor surface rust blooms.
South	3	L9-U9	Y	Vertical	Double angles w/ lattice web	No significant defects noted.
South	3	U9-L10	Y	Diagonal	Channels w/ tie and reinforcing plates	Near L10, the cover plate has a missing rivet (approximately 7 ft. above deck).
South	3	U9-U10	Y	Top Chord	Double channels w/ lattice web	No significant defects noted.
South	3	U10-U11	Y	Top Chord	Double channels w/ lattice web	No significant defects noted.
South	3	U11L10	N	Diagonal	Channels w/ tie and reinforcing plates	Near the top of the member, there is a missing rivet in a bottom lattice bar connection.
South	3	L10-L11	Y	Bottom Chord	Built up angles w/ lattice web	At L10, the gusset plate has four bolts replacing missing rivets. L10 bottom lateral gusset is reinforced with an angle iron, secured with a total of 12 bolts. There is rust and pitting in the gusset plate up to 1/8" deep along the top edge of the angle iron.
South	3	L11-U11	Y	Vertical	Double angles w/ lattice web	Vertical is pulled inward up to 1" at the old sway connection.
South	3	U11-L12	Y	Diagonal	Double channels w/ tie plates	At L12 there is surface rust on a members next to edge of exterior gusset plate.
South	3	L11-L12	Y	Bottom Chord	Built up angles w/ lattice web	No significant defects noted.
South	3	L12-L13	Y	Bottom Chord	Double channels w/ tie plates	Channel flanges are slightly bent in two locations near L12.
South	3	L13-U13	Y	Vertical	Double angles w/ lattice web	At U13 the gusset plate has minor rust pitting.
South	3	U13-L14	Y	Diagonal	Double channels w/ lattice web	No significant defects noted.
South	3	L13-L14	Y	Bottom Chord	Double channels w/ tie plates	No significant defects noted.
South	3	L14-U15	Y	Diagonal	Double channels w/ lattice web	No significant defects noted.
South	3	L14-L15	Y	Bottom Chord	Channels w/ tie and reinf. plates	No significant defects noted.
South	3	L15-U15	Y	Vertical	Double angles w/ lattice web	No significant defects noted.
South	3	L15-L16	Y	Bottom Chord	Channels w/ tie and reinforcing plates	No significant defects noted.

VISUAL FRACTURE CRITICAL INSPECTION REPORT

Truss Line	Span	Location	FC	Feature Inspected	Detail Description	Remarks
South	3	U15-L16	Y	Diagonal	Double channels w/ lattice web	Near the top, there is a missing rivet in a lacing bar connection. At U15, the north gusset plate interior face has minor rust pitting along the bottom edge up to 1/16" deep.
South	3	L16-U17	Y	Diagonal	Double channels w/ tie plates	No significant defects noted.
South	3	L16-L17	Y	Bottom Chord	Double channels w/ tie plates	No significant defects noted.
South	3	L17-U17	Y	Vertical	Double angles w/ lattice web	No significant defects noted.
South	3	L17-L18	Y	Bottom Chord	Double channels w/ tie plates	No significant defects noted.
South	3	L18-U19	Y	Diagonal	Double channels w/ tie plates	At L18 the south gusset plate has a misdrilled hole.
South	3	L18-L19	Y	Bottom Chord	Built up angles w/ lattice web	No significant defects noted.
South	3	L19-L20	Y	Bottom Chord	Built up angles w/ lattice web	At L20, the north gusset plate interior face at the bottom edge is corroded down to a knife edge over a 1-1/2" length. See photo #30.
South	3	L19-U19	Y	Vertical	Double angles w/ lattice web	Vertical member has a slight twist with the north flange bent up to 1" to the west at mid height.
South	3	U19-U20	Y	Top Chord	Channels w/ tie and reinforcing plates	No significant defects noted.
South	3	U20-U21	Y	Top Chord	Channels w/ tie and reinforcing plates	No significant defects noted.
South	3	L20-U21	Y	Diagonal	Channels w/ tie and reinforcing plates	No significant defects noted.
South	3	L21-U21	Y	Vertical	Double angles w/ lattice web	No significant defects noted.
South	3	U21	Y	Pin	18-3/4" x 5-3/4" dia. Shldr 17"	Pin has minor surface rust blooms.
South	3/4	U21-U23	Y	TC Eyebar	Solid Bar Stock	No significant defects noted.
South	4	U23	Y	Pin	18-3/4" x 5-3/4" dia. Shldr 17"	Pin has minor surface rust blooms.
South	4	U23-L23	Y	Vertical	Double angles w/ lattice web	No significant defects noted.
South	4	U23-L24	Y	Diagonal	Double channels w/ tie plates	No significant defects noted.
South	4	U23-U25	Y	Top Chord	Channels w/ lattice web and tie plates	No significant defects noted.
South	4	L24-L25	Y	Bottom Chord	Double channels w/ lattice web	No significant defects noted.
South	4	L25-L26	Y	Bottom Chord	Double channels w/ lattice web	No significant defects noted.
South	4	L25-U25	Y	Vertical	Double angles w/ lattice web	No significant defects noted.
South	4	U25-L26	Y	Diagonal	Double channels w/ tie plates	No significant defects noted.
South	4	U25-U26	Y	Top Chord	Channels w/ lattice web and tie plates	No significant defects noted.
South	4	L26-L27	Y	Bottom Chord	Built up angles w/ lattice web	At L26 there is seam rust along the inside splice plate.
South	4	L26-U27	N	Diagonal	Double channels w/ tie plates	Near L26 there is a missing rivet in a top lattice bar connection.
South	4	L27-U27	Y	Vertical	Double angles w/ lattice web	Vertical member is bent up to 1" to the west and 1" to the north at the old sway connection.

VISUAL FRACTURE CRITICAL INSPECTION REPORT

Truss Line	Span	Location	FC	Feature Inspected	Detail Description	Remarks
South	4	U26-U27	Y	Top Chord	Channels w/ lattice web and tie plates	No significant defects noted.
South	4	U27-L28	Y	Diagonal	Double channels w/ lattice web	No significant defects noted.
South	4	L27-L28	Y	Bottom Chord	Built up angles w/ lattice web	No significant defects noted.
South	4	L28-U29	Y	Diagonal	Built up angles w/ lattice web	No significant defects noted.
South	4	L28-L29	Y	Bottom Chord	Built up angles with tie plates	No significant defects noted.
South	4	L29-U29	Y	Vertical	Double angles with tie plates	No significant defects noted.
South	4	L29-L30	Y	Bottom Chord	Built up angles with tie plates	No significant defects noted.

VISUAL FRACTURE CRITICAL INSPECTION REPORT

Truss Line	Span	Location	FC	Feature Inspected	Detail Description	Remarks
North	2	L0-L1	Y	Bottom Chord	Built up angles w/ tie plates	No significant defects noted.
North	2	U1-L1	Y	Vertical	Double angles w/ tie plates	No significant defects noted.
North	2	U1-L2	Y	Diagonal	Built up angles w/ lattice web	No significant defects noted.
North	2	L1-L2	Y	Bottom Chord	Built up angles w/ tie plates	No significant defects noted.
North	2	L2-L3	Y	Bottom Chord	Built up angles w/ lattice web	No significant defects noted.
North	2	L2-U3	Y	Diagonal	Double channels w/ lattice web	No significant defects noted.
North	2	U3-L3	Y	Vertical	Double angles w/ lattice web	No significant defects noted.
North	2	U3-U4	Y	Top Chord	Channels w/ lattice web and tie plates	No significant defects noted.
North	2	U4-U5	Y	Top Chord	Channels w/ lattice web and tie plates	No significant defects noted.
North	2	L3-L4	Y	Bottom Chord	Built up angles w/ lattice web	At L4, the bottom lateral gusset plate has rust pitting on the top surface.
North	2	L4-U5	Y	Diagonal	Double channels w/ tie plates	No significant defects noted.
North	2	U5-L5	Y	Vertical	Double angles w/ lattice web	No significant defects noted.
North	2	L4-L5	Y	Bottom Chord	Double channels w/ lattice web	No significant defects noted.
North	2	L5-L6	Y	Bottom Chord	Double channels w/ lattice web	No significant defects noted.
North	2	U5-U7	Y	Top Chord	Channels w/ tie and reinforcing plates	No significant defects noted.
North	2	L6-U7	Y	Diagonal	Double channels w/ tie plates	No significant defects noted.
North	2	U7-L7	Y	Vertical	Double angles w/ lattice web	No significant defects noted.
North	2	U7	Y	Pin	18-3/4" x 5-3/4" dia. Shldr 17"	Pin has minor surface rust blooms.
North	2/3	U7-U9	Y	TC Eyebar	Solid Bar Stock	At U7 and U9 there is minor surface rust blooms around the pins.
North	3	U9	Y	Pin	18-3/4" x 5-3/4" dia. Shldr 17"	Pin has minor surface rust blooms.
North	3	L9-U9	Y	Vertical	Double angles w/ lattice web	No significant defects noted.
North	3	U9-L10	Y	Diagonal	Channels w/ lattice web and tie plates	At L10 the interior gusset plate has seam rust.
North	3	U9-U10	Y	Top Chord	Double channels w/ lattice web	No significant defects noted.
North	3	U10-U11	Y	Top Chord	Double channels w/ lattice web	No significant defects noted.
North	3	L10-L11	Y	Bottom Chord	Built up angles w/ lattice web	At L11 the interior face of the south gusset plate has minor rust pitting up to 1/16" deep.
North	3	L11-U11	Y	Vertical	Double angles w/ lattice web	No significant defects noted.
North	3	U11-L12	Y	Diagonal	Double channels w/ tie plates	No significant defects noted.
North	3	L11-L12	Y	Bottom Chord	Built up angles w/ lattice web	No significant defects noted.
North	3	L12-L13	Y	Bottom Chord	Double channels w/ tie plates	No significant defects noted.
North	3	L13-U13	Y	Vertical	Double angles w/ lattice web	No significant defects noted.
North	3	U13-L14	Y	Diagonal	Double channels w/ lattice web	No significant defects noted.
North	3	L13-L14	Y	Bottom Chord	Double channels w/ tie plates	No significant defects noted.
North	3	L14-U15	Y	Diagonal	Double channels w/ lattice web	No significant defects noted.
North	3	L14-L15	Y	Bottom Chord	Channels w/ tie and reinforcing plates	Splice plate at L14 is pitted.

VISUAL FRACTURE CRITICAL INSPECTION REPORT

Truss Line	Span	Location	FC	Feature Inspected	Detail Description	Remarks
North	3	L15-U15	Y	Vertical	Double angles w/ lattice web	Both angles have been repaired by welding splice plates to both legs. One angle is repaired at the rail and the other 3 ft. above the rail.
North	3	L15-L16	Y	Bottom Chord	Channels w/ tie and reinforcing plates	No significant defects noted.
North	3	U15-L16	Y	Diagonal	Double channels w/ lattice web	No significant defects noted.
North	3	L16-U17	Y	Diagonal	Double channels w/ tie plates	No significant defects noted.
North	3	L16-L17	Y	Bottom Chord	Double channels w/ tie plates	No significant defects noted.
North	3	L17-U17	Y	Vertical	Double angles w/ lattice web	There is a mis-drilled hole just above the sway frame connection.
North	3	L17-L18	Y	Bottom Chord	Double channels w/ tie plates	No significant defects noted.
North	3	L18-U19	Y	Diagonal	Double channels w/ tie plates	No significant defects noted.
North	3	L18-L19	Y	Bottom Chord	Built up angles w/ lattice web	No significant defects noted.
North	3	L19-L20	Y	Bottom Chord	Built up angles w/ lattice web	At L20 there is a missing rivet.
North	3	L19-U19	Y	Vertical	Double angles w/ lattice web	Vertical member is pulled to the west approximately 1" near mid-height.
North	3	U19-U20	Y	Top Chord	Channels w/ tie and reinforcing plates	No significant defects noted.
North	3	U20-U21	Y	Top Chord	Channels w/ tie and reinforcing plates	No significant defects noted.
North	3	L20-U21	Y	Diagonal	Channels w/ tie and reinforcing plates	Near mid height, the exterior coverplate is bent outward 1/4" over a 12" length on the bottom edge and the adjacent rivet head is missing.
North	3	L21-U21	Y	Vertical	Double angles w/ lattice web	No significant defects noted.
North	3	U21	Y	Pin	18-3/4" x 5-3/4" dia. Shldr 17"	Pin has minor surface rust blooms.
North	3/4	U21-U23	Y	TC Eyebar	Solid Bar Stock	No significant defects noted.
North	4	U23	Y	Pin	18-3/4" x 5-3/4" dia. Shldr 17"	Pin has minor surface rust blooms.
North	4	U23-L23	Y	Vertical	Double angles w/ lattice web	No significant defects noted.
North	4	U23-L24	Y	Diagonal	Double channels w/ tie plates	No significant defects noted.
North	4	U23-U25	Y	Top Chord	Channels w/ lattice web and tie plates	No significant defects noted.
North	4	L24-L25	Y	Bottom Chord	Double channels w/ lattice web	No significant defects noted.
North	4	L25-L26	Y	Bottom Chord	Double channels w/ lattice web	No significant defects noted.
North	4	L25-U25	Y	Vertical	Double angles w/ lattice web	No significant defects noted.
North	4	U25-L26	Y	Diagonal	Double channels w/ tie plates	No significant defects noted.
North	4	U25-U26	Y	Top Chord	Channels w/ lattice web and tie plates	No significant defects noted.
North	4	L26-L27	Y	Bottom Chord	Built up angles w/ lattice web	At L26 there is seam rust along the inside splice plate.

VISUAL FRACTURE CRITICAL INSPECTION REPORT

Truss Line	Span	Location	FC	Feature Inspected	Detail Description	Remarks
North	4	L27-U27	Y	Vertical	Double angles w/ lattice web	Vertical member is pulled 1" to the west and south at the old sway brace connection with several buckled lacing bars due to previous traffic impact. Approximately 2 ft. below the sway, tie plate is missing 8 rivets and tie plate is now welded.
North	4	U26-U27	Y	Top Chord	Channels w/ lattice web and tie plates	No significant defects noted.
North	4	U27-L28	Y	Diagonal	Double channels w/ lattice web	No significant defects noted.
North	4	L27-L28	Y	Bottom Chord	Built up angles w/ lattice web	No significant defects noted.
North	4	L28-U29	Y	Diagonal	Built up angles w/ lattice web	Near mid height there is a missing rivet in a lattice bar connection.
North	4	L28-L29	Y	Bottom Chord	Built up angles with tie plates	No significant defects noted.
North	4	L29-U29	Y	Vertical	Double angles with tie plates	No significant defects noted.
North	4	L29-L30	Y	Bottom Chord	Built up angles with tie plates	No significant defects noted.

Bridge Name:	SKAGIT R MARBLEMOUNT	Date:	3/4/2020
Bridge No:	40070	Hours:	2.0
Structure ID:	08228800	Inspector ID #:	G1303
Structure Type:	STRus PCMWG	Lead Inspector Initials:	TKK
Agency:	SKAGIT COUNTY	Co-Inspector Initials:	WAW
Milepost:	0.03		


Inspected items: Pins

Procedures:

1. When possible, test from both ends of pins.
2. Verify pin length shown on back reflection with plans. If back reflection does not match the plans, conduct manual length measurement and document correct pin length.
3. Start test with transducer at or near pin center for back reflection check, then run transducer around full perimeter of pin, searching for indications or significant loss of back reflection.
4. Whenever the test suggests that there is a defect in a pin, store and print out the indication with all associated equipment and settings documented. The location of the transducer shall also be documented using a clock hand convention (1 O'clock to 12 O'clock).

UTM Location	UTM Type	UTM Per Truss Line	BEIST Server Plans		
			Sh. No.	Contract	Sh. Name
U7, U9, U21, U23 of the North and South Trusses	Pins	4			

Note: UTM = Ultrasonic Tested Member



STRUCTURE I.D.	08228800
TRUSS I.D.	SOUTH
PIN I.D.	U7

DATE 3/4/2020 0.75 x 2.25 MHz Transducer

<<<<<<<< LEFT END >>>>>>>> <<<<<<<< RIGHT END >>>>>>>>


COMMENTS: No Indications Noted

WASHINGTON STATE DEPARTMENT OF TRANSPORTATION BRIDGE PRESERVATION


BRIDGE NAME: SKAGIT RIVER MARBLEMOUNT
 BRIDGE NO.: 40070
 LEAD INSPECTOR: JOHN H LABRANCH
 CO-INSPECTOR SEAN M TANNER
 UT MODEL: KK USN 52L
 UT SERIAL NO.: 29C69009

DATE: 03/29/2006
 STRUCTURE ID: 08228800
 INSPECTOR NUMBER: A1044
 TRANSDUCER USED: 0.75in.
 TRANSDUCER MODEL: PANAME
 TRANSDUCER SERIAL NO.: XXXXX


GAIN: 59.7 dB
 RANGE: 20.00 in
 MTL VEL: .2301/us
 DAC/TCG: OFF
 DAC ECHO: 0
 DELAY: 0.000 us
 REP-RATE: LOW
 DAMPING: 1000 OHM
 S-REF1: 1.000 in
 S-REF2: 4.000 in
 MEASURE: 0 TO 1st
 a-THRESH: 12 %
 TOP: FLANK
 a-START: 16.04 in
 ASCAN: HOLLOW
 a-WIDTH: 2.404 in
 b-THRESH: 30 %
 ZERO: 0.300 us
 DATA SET: 77
 b-START: 10 %
 ANGLE: OFF
 X-VALUE: 0.000 in
 THICKNESS: 0.500 in
 AMPLITUDE: % SCREEN HT
 FREEZE MODE: FREEZE ALL
 VELOCITY #1: .2320/us



USMGO\MM1.JPG
 03/25/2014 12:19:28 INSTRUMENT ID USMGO10060278 V2.02
 GAIN 0.2
 63.4 dB



RANGE	PULSER	RECEIVER	dB REF	AUTOCAL	GATE A	GATE B
19.500 in	HIGH	2.25 MHz	63.4 dB	OFF	70%	50%
1.005 us	RECTIFY	NEG HALF WAVE	REF VALUE	1500 Hz	70%	50%
.2336 in/us	FREQUENCY	RECTIFY	REF VALUE	1500 Hz	70%	50%
4.350 us	PRF MODE	NEG HALF WAVE	REF VALUE	1500 Hz	70%	50%
	AUTO HIGH	1500 Hz				
	GATE A START	GATE A WIDTH	GATE A TRSH	TOF MODE		
	17.500 in	2.116 in	70%	FLANK		
	GATE B START	GATE B WIDTH	GATE B TRSH	TOF MODE		
	15.911 in	1.903 in	50%	FLANK		
	PROBE ANGLE	THICKNESS	X VALUE	O-DIAMETER		
	OFF	1.969 in	0.000 in	FLAT		
	GAIN	REF GAIN	TRANSFER CORR.			
	63.4 dB	0.0 dB	0.0 dB			
	FILE	LAST DATASET LOADED				




COMMENTS: <<<<<<< LEFT END >>>>>>>

COMMENTS: <<<<<<< RIGHT END >>>>>>>

BASIC RCVR PULS GATE S-CAL TCG

dB REF 5 MODE OFF REFERENCE (NO REF)



DATE 3/4/2020 0.75 x 2.25 MHz Transducer

<<<<<<< LEFT END >>>>>>>> <<<<<<< RIGHT END >>>>>>>>

COMMENTS: No Indications Noted No Indications Noted

WASHINGTON STATE DEPARTMENT OF TRANSPORTATION BRIDGE PRESERVATION

BRIDGE NAME: SKAGIT RIVER MARBLEMOUNT DATE: 03/29/2006
 BRIDGE NO: 40070 STRUCTURE ID: 08228800
 LEAD INSPECTOR: JOHN H LABRANCH INSPECTOR NUMBER: A1044
 CO-INSPECTOR: SEAN W TANNER TRANSDUCER USED: 0.75in.
 UT MODEL: KK USN 52L TRANSDUCER MODEL: PANAMET
 UT SERIAL NO.: 29C69009 TRANSDUCER SERIAL NO.: XXXXX

GAIN: 65.7 dB DAC/TCG: OFF DAC ECHO: 0
 RANGE: 19.97 in MTL VEL: .2300/us DELAY: 0.000 us
 FREQ.: .3-4 MHz REP-RATE: LOW DAMPING: 1000 OHM
 AUTO CAL: OFF S-REF1: 1.000 in S-REF2: 4.000 in

PULSER: SINGLE MEASURE: 0 TO 1st a-THRESH: 12 %
 REJECT: 0 % TOP: FLANK a-START: 15.50 in
 RECTIF.: FULL ASCAN: HOLLOW a-WIDTH: 2.404 in

b-THRESH: 30 % ZERO: 0.300 us DATA SET: 79
 b-START: 10 % ANGLE: OFF X-VALUE: 0.000 in

THICKNESS: 0.500 in
 AMPLITUDE: % SCREEN HT
 FREEZE MODE: FREEZE ALL
 VELOCITY #1: .2320/us


GAIN 1.0
65.7 dB
RECALL OFF
SET# 79
STORE OFF

USMGO\MM2.JPG 03/25/2014 12:39:15 INSTRUMENT ID USMGO10060278 V2.02

GAIN 0.2 R% = 92 % R%B = 82 % Sba = 1.708 in


63.4 dB SR/ = 18.841 in SB/ = 17.188 in

RANGE	PULSER	RECEIVER	dB REF	AUTOCAL	GATE A	GATE B
CV Parameter Table						
RANGE	RANGE	PROBE DELAY	VELOCITY	DISPLAY DELAY		
PULSER	VOLTAGE	HIGH	DAMPING			
REC	FREQUENCY	RECTIFY	DUAL	REJECT		
PRF	PRF MODE	PRF VALUE				
GATES	GATE A START	GATE A WIDTH	GATE A TRSH	TOF MODE		
	GATE B START	GATE B WIDTH	GATE B TRSH	TOF MODE		
TRIG	PROBE ANGLE	THICKNESS	X VALUE	O-DIAMETER		
GAIN	GAIN	REF GAIN	TRANSFER CORR.			
FILE	LAST DATASET LOADED					



DATE 3/4/2020 0.75 x 2.25 MHZ Transducer

<<<<<<< LEFT END >>>>>>>	<<<<<<< RIGHT END >>>>>>>
COMMENTS:	COMMENTS:
	dB REF 5 REFERENCE MODE (NO REF) OFF



DATE 3/4/2020 0.75 x 2.25 MHz Transducer

<<<<<<< LEFT END >>>>>>>> <<<<<<< RIGHT END >>>>>>>>

COMMENTS: No Indications Noted No Indications Noted

<p style="text-align: center; font-weight: bold;">WASHINGTON STATE DEPARTMENT OF TRANSPORTATION BRIDGE PRESERVATION</p> <p>BRIDGE NAME: SKAGIT RIVER MARBLEMOUNT DATE: 03/29/2006 BRIDGE NO: 40070 STRUCTURE ID: 08228800 LEAD INSPECTOR: JOHN H LABRANCH INSPECTOR NUMBER: A1044 CO-INSPECTOR SEAN M TANNER TRANSDUCER USED: 0.75in. UT MODEL: KK USN 52L TRANSDUCER MODEL: PANAMET UT SERIAL NO.: 29C69009 TRANSDUCER SERIAL No.: XXXXX</p> <p>GAIN: 60.7 dB DAC/TCG: OFF DAC ECHO: 0 RANGE: 19.97 in MTL VEL: .2300/us DELAY: 0.000 us FREQ.: .3-4 MHz REP-RATE: LOW DAMPING: 1000 OHM AUTO CAL: OFF S-REF1: 1.000 in S-REF2: 4.000 in</p> <p>PULSER: SINGLE MEASURE: 0 TO 1st a-THRESH: 12 % RECTIF.: 0 % TOP: FLANK a-START: 15.50 in RECTIF.: FULL ASCAN: HOLLOW a-WIDTH: 2.404 in</p> <p>b-THRESH: 30 % ZERO: 0.300 us DATA SET: 80 b-START: 10 % ANGLE: OFF X-VALUE: 0.000 in</p> <p>THICKNESS: 0.500 in AMPLITUDE: % SCREEN HT FREEZE MODE: FREEZE ALL VELOCITY #1: .2320/us</p> <p style="text-align: right;">GAIN 60.7 dB RECALL OFF SET# 80 STORE OFF</p>	<p style="text-align: center; font-weight: bold;">WASHINGTON STATE DEPARTMENT OF TRANSPORTATION BRIDGE PRESERVATION</p> <p>BRIDGE NAME: SKAGIT RIVER BR. DATE: 3/19/2008 BRIDGE NUMBER: 40070 STRUCTURE ID: 08228800 LEAD INSPECTOR: Hubert Ritter INSPECTOR #: G0004 CO-INSPECTOR: Ward Wegner TRANSDUCER USED: 0.75" x 2.25 Mhz UT MODEL: USN 52L TRANSDUCER MODEL: Panametrics UT SERIAL #: 29C69010</p> <p>GAIN: 50.5 dB DAC/TCG: OFF DAC ECHO: 0 RANGE: 19.00 in MTL VEL: .2309/us DELAY: 0.000 us FREQ.: .3-4 MHz REP-RATE: LOW DAMPING: 1000 OHM AUTO CAL: OFF S-REF1: 1.000 in S-REF2: 4.000 in</p> <p>PULSER: SINGLE MEASURE: 0 TO 1st a-THRESH: 10 % RECTIF.: 0 % TOP: FLANK a-START: 16.63 in RECTIF.: FULL ASCAN: HOLLOW a-WIDTH: 0.923 in</p> <p>b-THRESH: 30 % ZERO: 0.311 us DATA SET: 16 b-START: 10 % ANGLE: OFF X-VALUE: 0.000 in</p> <p>THICKNESS: 0.500 in AMPLITUDE: % SCREEN HT FREEZE MODE: FREEZE ALL VELOCITY #1: .2320/us</p> <p style="text-align: right;">GAIN 50.5 dB RECALL OFF SET# 16 STORE OFF</p>
--	---

DATE 3/4/2020 0.75 x 2.25 MHZ Transducer

<<<<<<< LEFT END >>>>>>>


<<<<<<< RIGHT END >>>>>>>

COMMENTS:


COMMENTS:

BASIC RCVR PULS GATE S-CAL TCG


BASIC RCVR PULS GATE S-CAL TCG




<<<<<<< LEFT END >>>>>>>	<<<<<<< RIGHT END >>>>>>>
COMMENTS:	COMMENTS:
No Indications Noted	No Indications Noted



RANGE	PULSER	RECEIVER	dB REF	AUTOCAL	GATE A	GATE B
CV Parameter Table						
RANGE	RANGE	PROBE DELAY	VELOCITY	DISPLAY DELAY		
PULSER	VOLTAGE	DAMPING	50 OHM			
REC V	FREQUENCY	RECTIFY	DUAL	REJECT		
PRF	PRF MODE	PRF VALUE	OFF	0%		
GATES	GATE A START	GATE A WIDTH	GATE A TRSH	TOF MODE		
	GATE B START	GATE B WIDTH	GATE B TRSH	TOF MODE		
TRIG	PROBE ANGLE	THICKNESS	X VALUE	O-DIAMETER		
GAIN	GAIN	REF GAIN	TRANSFER CORR.			
FILE	LAST DATASET LOADED					




RANGE	PULSER	RECEIVER	dB REF	AUTOCAL	GATE A	GATE B
CV Parameter Table						
RANGE	RANGE	PROBE DELAY	VELOCITY	DISPLAY DELAY		
PULSER	VOLTAGE	DAMPING	50 OHM			
REC V	FREQUENCY	RECTIFY	DUAL	REJECT		
PRF	PRF MODE	PRF VALUE	OFF	0%		
GATES	GATE A START	GATE A WIDTH	GATE A TRSH	TOF MODE		
	GATE B START	GATE B WIDTH	GATE B TRSH	TOF MODE		
TRIG	PROBE ANGLE	THICKNESS	X VALUE	O-DIAMETER		
GAIN	GAIN	REF GAIN	TRANSFER CORR.			
FILE	LAST DATASET LOADED					



DATE 3/4/2020 0.75 x 2.25 MHZ Transducer

<<<<<<< LEFT END >>>>>>>	<<<<<<< RIGHT END >>>>>>>
COMMENTS:	COMMENTS:

dB REF	5	MODE	REFERENCE	dB REF	MODE	REFERENCE
	OFF		(NO REF)		OFF	(NO REF)




DATE 3/4/2020 0.75 x 2.25 MHz Transducer

<<<<<< LEFT END >>>>>>

COMMENTS: No Indications Noted

\\USMGO\MM2 008.JPG 03/26/2014 12:45:18 INSTRUMENT ID USMGO10060278 V2.02



RANGE	PULSER	RECEIVER	dB REF	AUTOCAL	GATE A	GATE B
CV Parameter Table						
RANGE	RANGE	PROBE DELAY	VELOCITY	DISPLAY DELAY		
PULSER	VOLTAGE	HIGH	DAMPING			
RECV	FREQUENCY	RECTIFY	DUAL	REJECT		
PRF	PRF MODE	PRF VALUE				
GATES	GATE A START	GATE A WIDTH	GATE A TRSH	TOF MODE		
TRIG	PROBE ANGLE	THICKNESS	X VALUE	O-DIAMETER		
GAIN	GAIN	REF GAIN	TRANSFER CORR.			
FILE	LAST DATASET LOADED					

<<<<<< RIGHT END >>>>>>

COMMENTS: No Indications Noted

WASHINGTON STATE DEPARTMENT OF TRANSPORTATION BRIDGE PRESERVATION

BRIDGE NAME: SKAGIT RIVER MARBLEMOUNT
 BRIDGE NO: 40070
 LEAD INSPECTOR: JOHN H LABRANCH
 CO-INSPECTOR SEAN M TANNER
 UT MODEL: KK USN 52L
 UT SERIAL NO.: 29C69009


DATE: 03/29/2006
 STRUCTURE ID: 08228800
 INSPECTOR NUMBER: A1044
 TRANSDUCER USED: 0.75in.
 TRANSDUCER MODEL: PANAMET
 TRANSDUCER SERIAL NO.: XXXXX


GAIN: 53.7 dB
 RANGE: 20.00 in
 FREQ.: .3-4 MHz
 AUTO CAL: OFF
 PULSER: SINGLE
 REJECT: 0 %
 RECTIF: FULL
 b-THRESH: 30 %
 b-START: 10 %

DAC/TCG: OFF
 MTL VEL: .2301/us
 REP-RATE: LOW
 S-REF1: 1.000 in
 MEASURE: 0 TO 1st
 TOF: FLANK
 ASCAN: HOLLOW
 ZERO: 0.200 us
 ANGLE: OFF

DAC ECHO: 0
 DELAY: 0.000 us
 DAMPING: 1000 OHM
 S-REF2: 4.000 in
 a-THRESH: 12 %
 a-START: 16.04 in
 a-WIDTH: 2.404 in
 DATA SET: 76
 X-VALUE: 0.000 in

THICKNESS: 0.500 in
 AMPLITUDE: % SCREEN HT
 FREEZE MODE: FREEZE ALL
 VELOCITY #1: .2320/us





<<<<<<< LEFT END >>>>>>>


COMMENTS:

dB REF	MODE OFF	REFERENCE (NO REF)
--------	----------	--------------------

<<<<<<< RIGHT END >>>>>>>

COMMENTS:



* BASIC RCVR PULS GATE S-CAL TCG




DATE 3/4/2020 0.75 x 2.25 MHz Transducer

COMMENTS: <<<<<<< LEFT END >>>>>>>
No Indications Noted


COMMENTS: <<<<<<< RIGHT END >>>>>>>
No Indications Noted





DATE 3/4/2020 0.75 x 2.25 MHZ Transducer

<<<<<<< LEFT END >>>>>>>	<<<<<<< RIGHT END >>>>>>>
COMMENTS:	COMMENTS:
dB REF MODE REFERENCE	* ↗ ↘ = BASIC RCVR PULS GATE S-CAL TCG
OFF (NO REF)	



DATE 3/4/2020 0.75 x 2.25 MHz Transducer

<<<<<<< LEFT END >>>>>>>

COMMENTS: No Indications Noted

<<<<<<< RIGHT END >>>>>>>

COMMENTS: No Indications Noted

USMGO\MM2 007.JPG
03/26/2014 11:28:29 INSTRUMENT ID USMGO10060278 V2.02

GAIN 0.2 96% 70% Sba= 1.694 in
49.6 dB Sd= 18.792 in SB= 17.098 in

range 19.500 in
PROBE DELAY 1.005 µs
velocity .2336 in/US
DISPLAY DELAY 4.325 µs

RANGE	PULSER	RECEIVER	dB REF	AUTOCAL	GATE A	GATE B
CV Parameter Table						
RANGE	RANGE	PROBE DELAY	VELOCITY	DISPLAY DELAY		
19.500 in	1.005 µs	.2336 in/US	4.325 µs			
PULSER	VOLTAGE	DAMPING				
HIGH	50 OHM					
RECV	FREQUENCY	RECTIFY	DUAL	REJECT		
2.25 MHz	NEG HALF WAVE	OFF	0%			
PRF	PRF MODE	PRF VALUE				
AUTO HIGH	1500 Hz					
GATES	GATE A START	GATE A WIDTH	GATE A TRSH	TOF MODE		
17.500 in	2.116 in	70%	FLANK			
GATE B START	GATE B WIDTH	GATE B TRSH	TOF MODE			
15.911 in	1.903 in	50%	FLANK			
TRIG	PROBE ANGLE	THICKNESS	X VALUE	O-DIAMETER		
OFF	1.969 in	0.000 in	FLAT			
GAIN	GAIN	REF GAIN	TRANSFER CORR.			
49.6 dB	0.0 dB	0.0 dB				
FILE	LAST DATASET LOADED					

WASHINGTON STATE DEPARTMENT OF TRANSPORTATION BRIDGE PRESERVATION

BRIDGE NAME: SKAGIT RIVER MARBLEMOUNT
BRIDGE NO: 40070
LEAD INSPECTOR: JOHN H LABRANCH
CO-INSPECTOR: SEAN M TANNER
UT MODEL: KK USN 52L
UT SERIAL NO.: 29C69009

DATE: 03/29/2006
STRUCTURE ID: 08228800
INSPECTOR NUMBER: A1044
TRANSDUCER USED: 0.75in.
TRANSDUCER MODEL: PANAMET
TRANSDUCER SERIAL NO.: XXXXX

GAIN: 55.7 dB DAC/TCG: OFF DAC ECHO: 0
RANGE: 20.00 in MTL VEL: .2301/us DELAY: 0.000 us
FREQ.: .3-4 MHz REP-RATE: LOW DAMPING: 1000 OHM
AUTO CAL: OFF S-REF1: 1.000 in S-REF2: 4.000 in
PULSER: SINGLE MEASURE: 0 TO 1st a-THRESH: 46 %
REJECT: 0 % TOP: FLANK a-START: 15.87 in
RECTIP.: PULL ASCAN: HOLLOW a-WIDTH: 2.395 in
b-THRESH: 30 % ZERO: 0.300 us DATA SET: 71 00Y3NTB
b-START: 10 % ANGLE: OFF X-VALUE: 0.000 in

THICKNESS: 0.500 in
AMPLITUDE: % SCREEN HT
FREEZE MODE: FREEZE ALL
VELOCITY #1: .2320/us

16.98 in




GAIN 1.0
55.7 dB


RECALL OFF

SET# 71
00Y3NTB

STORE OFF

DATE 3/4/2020 0.75 x 2.25 MHZ Transducer

<<<<<<< LEFT END >>>>>>>	<<<<<< RIGHT END >>>>>>>
COMMENTS:	COMMENTS:
dB REF 5 REFERENCE MODE OFF (NO REF)	*    TCG



DATE 3/4/2020 0.75 x 2.25 MHz Transducer

<<<<<<< LEFT END >>>>>>>

COMMENTS: No Indications Noted

<<<<<<< RIGHT END >>>>>>>

COMMENTS: No Indications Noted

USMGO\MM2 003.JPG
03/26/2014 11:11:58 INSTRUMENT ID USMGO10060278 V2.02

GAIN 44.0 dB SRF= 18.984 in SBF= 17.128 in Sba= 1.811 in

range 19.500 in

PROBE DELAY 1.005 μ s

velocity .2336 in/uS

DISPLAY DELAY 4.350 μ s

RANGE	PULSER	RECEIVER	dB REF	AUTOCAL	GATE A	GATE B
CV Parameter Table						
RANGE	RANGE	PROBE DELAY	VELOCITY	DISPLAY DELAY		
19.500 in	19.500 in	1.005 μ s	.2336 in/uS	4.350 μ s		
PULSER	VOLTAGE	HIGH	DAMPING			
	2.25 MHz	NEG HALF WAVE	50 OHM			
PRF	FREQUENCY	RECTIFY	DUAL	REJECT		
	2.25 MHz	NEG HALF WAVE	OFF	0%		
GATES	GATE A START	GATE A WIDTH	GATE A TRSH	TOF MODE		
	17.500 in	2.116 in	70%	FLANK		
	GATE B START	GATE B WIDTH	GATE B TRSH	TOF MODE		
	15.911 in	1.903 in	50%	FLANK		
TRIG	PROBE ANGLE	THICKNESS	X VALUE	O-DIAMETER		
	OFF	1.969 in	0.000 in	FLAT		
GAIN	GAIN	REF GAIN	TRANSFER CORR.			
	44.0 dB	0.0 dB	0.0 dB			
FILE	LAST DATASET LOADED					

WASHINGTON STATE DEPARTMENT OF TRANSPORTATION BRIDGE PRESERVATION

BRIDGE NAME: SKAGIT RIVER MARBLEMOUNT DATE: 03/29/2006
 BRIDGE NO: 40070 STRUCTURE ID: 08228800
 LEAD INSPECTOR: JOHN H LABRANCH INSPECTOR NUMBER: A1044
 CO-INSPECTOR SEAN M TANNER TRANSDUCER USED: 0.75in.
 UT MODEL: KK USN 52L TRANSDUCER MODEL: PANAMET
 UT SERIAL NO.: 29C69009 TRANSDUCER SERIAL NO.: XXXXX

GAIN: 45.7 dB DAC/TCG: OFF DAC ECHO: 0
 RANGE: 20.00 in MTL VEL: .2301/us DELAY: 0.000 us
 FREQ.: .3-4 MHz REP-RATE: LOW DAMPING: 1000 OHM
 AUTO CAL: OFF S-REF1: 1.000 in S-REF2: 4.000 in
 PULSER: SINGLE MEASURE: 0 TO 1st a-THRESH: 46 %
 REJECT: 0 % TOF: FLANK a-START: 15.87 in
 RECTIF.: FULL ASCAN: HOLLOW a-WIDTH: 2.395 in
 b-THRESH: 30 % ZERO: 0.300 us DATA SET: 70 00Y3NTA
 b-START: 10 % ANGLE: OFF X-VALUE: 0.000 in

THICKNESS: 0.500 in
 AMPLITUDE: % SCREEN HT
 FREEZE MODE: FREEZE ALL
 VELOCITY #1: .2320/us


17.04 in

GAIN 45.7 dB

RECALL OFF

SET# 70
00Y3NTA

STORE OFF



DATE 3/4/2020 0.75 x 2.25 MHZ Transducer

<<<<<<< LEFT END >>>>>>>

COMMENTS:

dB REF	MODE OFF	REFERENCE (NO REF)
--------	----------	--------------------

<<<<<<< RIGHT END >>>>>>>

COMMENTS:

* BASIC RCVR PULS GATE S-CAL TCG



PIN SUMMAR SHEET

Bridge Name: SKAGIT R MARBLEMOUNT
 Bridge No.: 40070
 Structure ID: 08228800
 Structure Type: STRus PCMWB
 Agency: SKAGIT COUNTY
 Milepost: 0.03

Date: 3/4/2020
 Hours: 2.0
 Inspector ID #: G1303
 Lead Inspector: TKK
 Co-Inspector: WAW

Truss Line	Span	Location	Detail Description	Condition State (worst case)							
				200	200	20 0	20 2	20 4	20	20	2020
South	2	U7	18-3/4 long 5-3/4 dia. Shoulder at 17	2	2	2	2	1	1	1	1
South	3	U9	18-3/4 long 5-3/4 dia. Shoulder at 17	2	2	2	2	1	1	1	1
South	3	U21	18-3/4 long 5-3/4 dia. Shoulder at 17	2	2	2	2	1	1	1	1
South	4	U23	18-3/4 long 5-3/4 dia. Shoulder at 17	3	2	2	2	1	1	1	1
North	2	U7	18-3/4 long 5-3/4 dia. Shoulder at 17	2	2	2	2	1	1	1	1
North	3	U9	18-3/4 long 5-3/4 dia. Shoulder at 17	2	2	2	2	1	1	1	1
North	3	U21	18-3/4 long 5-3/4 dia. Shoulder at 17	3	2	2	2	1	1	1	1
North	4	U23	18-3/4 long 5-3/4 dia. Shoulder at 17	2	2	2	2	1	1	1	1



Skagit County Public Works

Appendix E – Scour Evaluation



Bridge Number 40070	Bridge Name Skagit River Marblemount	Structure ID 08228800
Date 3/4/2020	Lead Inspector TKK	Co-Inspector WAW

<input type="checkbox"/> Heavy Growth Along Banks <input checked="" type="checkbox"/> Ice/Debris in Channel <input type="checkbox"/> Channel/Embankments are Eroding/Sloughing <input type="checkbox"/> Damage to Riprap/Abutments/Piers <input type="checkbox"/> Scour Holes Near Piers/Abutments <input type="checkbox"/> Riprap in Place at Piers/Abutments	<input type="checkbox"/> Boat Required <input type="checkbox"/> Divers Required <input type="checkbox"/> UBIT Required <input type="checkbox"/> Winter Inspection <input checked="" type="checkbox"/> Repair Required <input type="checkbox"/> Monitoring Required
---	---

Soundings		Thalweg (ft):	36.0
Taken from top of the upstream bridge rail		Distance to thalweg (ft):	0.0
Location	Measurement ft	Distance was measured from:	Panel Point 19
Panel Point 0 (Pier 2)	18.0	Rail Height from Deck (ft):	39.0"
Panel Point 1	18.0	Inspector's Remarks:	
Panel Point 2	19.0		
Panel Point 3	18.5	Rail measured to 39" over the top of the deck.	
Panel Point 4	20.0		
Panel Point 5	20.2		
Panel Point 6	20.8		
Panel Point 7 (West Bank)	26.0		
Panel Point 8 (Pier 3)	31.0		
Panel Point 9	30.0		
Panel Point 10	30.0		
Panel Point 11	31.0		
Panel Point 12	31.0		
Panel Point 13	31.0		
Panel Point 14	32.0		
Panel Point 15	32.0		
Panel Point 16	32.0		
Panel Point 17	33.0		
Panel Point 18	34.0		
Panel Point 19	36.0	Repairs Warranted:	
Panel Point 20	34.0		
Panel Point 21	34.0		
Panel Point 22 (Pier 4)	32.0	Remove debris accumulation from Pier 4.	
Panel Point 23	30.0		
Panel Point 24 (East Bank)	25.0		
Panel Point 25	21.0		
Panel Point 26	20.2		
Panel Point 27	20.0		
Panel Point 28	20.0		
Panel Point 29	17.0		
Panel Point 30 (Pier 5)	17.0		



Date 7/9/2019	Agency Skagit County		
Bridge Number 40070	Bridge Name SKAGIT RIVER MARBLEMOUNT - SID 08228800		
Evaluated By Grant Griffin			
Superstructure Type Steel Through Truss	Superstructure Continuity? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Any Spread Footings? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	

Evaluation

Yes No

Estimated from Records

Evaluation: Are foundation elevations known? If not, consider the bridge scour critical (using engineering judgment and any other information available).

Yes No

Evaluation: Does the thalweg (the deepest portion of the stream; the main channel) meander back and forth across the floodplain? If so, the potential for a scour critical condition is increased.

Yes No

Evaluation: For a spread footing, is the bottom of the seal (or footing, if the seal is not used) above the thalweg? If so, the bridge is scour critical; no need to proceed further.

Yes No

Evaluation: For a pile supported footing, is the pile tip elevation 10 feet or less below the thalweg? If so the bridge is scour critical; no need to proceed further.

Bridge Is Scour Critical Yes No

Evaluation Criteria

- Foundation elevations are (or are not) known and available.
- The thalweg meanders back and forth across the floodplain.
- Pier scour is always measured from the thalweg, even if the pier is in the overbank.
- For a spread footing, if the calculated depth of scour is below the footing, the bridge is scour critical.
- For a pile supported footing, if calculated depth of scour is 10' or less above pile tip elevation, the bridge is scour critical.
- Scour should be calculated for 100 year flood. If not shown on bridge plan layout, check FEMA map. If not mapped by FEMA, use high water shown on layout or the USGS Regression equations found in the WSDOT Hydraulics Manual (M23-03).

Evaluate End Abutments for Scour

- Adequate and practical formulae for determining anticipated local scour due to an end abutment do not exist; each bridge must be evaluated individually.
- Existing riprap should be evaluated by the bridge inspector.
- If there is no riprap in place, **or** if existing riprap appears to be in place, and **can be bypassed** by migration of the stream at the upstream end of the riprap, treat the end abutment like an interior pier.
- If existing riprap appears to be in place, and **cannot be bypassed** by migration of the stream at the upstream end of the riprap, the bridge **is not** scour critical.


Bridge Is Scour Critical Yes No

Bridge No. 40070, the Marblemount Bridge over the Skagit River, is a 662-foot-long steel through truss supported on piers with footings supported by driven timber piles. High flows are being controlled by the dams on the river and the County has a response plan for predicted storm events to control the flow and manage high volume events. Piers 2 and 3 are in the flow of the river but close enough to the shore to inspect the footings and check for scour. Inspection notes indicate some footing exposure that is usually followed by aggregation of any scouring. Debris build-up can be a problem and the County Maintenance forces work to keep the debris clear. **By this assessment, field 1680 is coded "8" consistent with a scour evaluation dated 1996 and the scour inspection history at the bridge.**



Skagit County Public Works

Appendix F – Traffic Data





Skagit County Public Works

Appendix G – Bridge Rehabilitation Cost Estimate



**Skagit River Marblemount Bridge Opinion of Cost
Painting, Gusset Plate Replacement, and Expansion Joint Replacement**

ITEM DESCRIPTION	QUANTITY	MEAS. UNIT	UNIT PRICE	COST
SPOT ABRASIVE BLASTING	10,000	SF	\$ 2	\$ 20,000
CLEANING AND PAINTING	100,000	SF	\$ 40	\$ 4,000,000
WORK PLATFORM	1	LS	\$ 1,000,000	\$ 1,000,000
CONTAINMENT OF ABRASIVES	52,800	SF	\$ 5	\$ 264,000
TESTING AND DISPOSAL OF CONTAINMENT WASTE	1	LS	\$ 20,000	\$ 20,000
CLEANING SEALING AND CAULKING PACK RUST	10,000	LF	\$ 10	\$ 100,000
HEALTH AND SAFETY PLAN	1	LS	\$ 15,000	\$ 15,000
WILDLIFE MANAGEMENT	1	LS	\$ 25,000	\$ 25,000
BEARING REPAIR	4	EA	\$ 5,000	\$ 20,000
GUSSET PLATE REPAIR	112	EA	\$ 16,000	\$ 1,792,000
ENGINEER DIRECTED REPAIRS	1	FA	\$ 250,000	\$ 250,000
STRUCTURAL STEEL REPAIR	10,000	LBS	\$ 15	\$ 150,000
EXPANSION JOINT REPLACEMENT	88	LF	\$ 1,000	\$ 88,000
SEALING JOINTS	264	LF	\$ 20	\$ 5,280
TRAFFIC ONTROL	1	LS	\$ 250,000	\$ 250,000
TESC	1	LS	\$ 25,000	\$ 25,000
SWPPP	1	LS	\$ 5,000	\$ 5,000
SPCC	1	LS	\$ 25,000	\$ 25,000
APPROACH RAILING REPLACEMENT	100	LF	\$ 150	\$ 15,000
CORE CONSTRUCTION COST				\$ 8,070,000
MOBILIZATION (10%)	1	LS		\$ 807,000.00
CONTINGENCIES (15%)	1	LS		\$ 1,211,000.00
ENGINEERING (25%)	1	LS		\$ 3,093,000.00
CONSTRUCTION ENGINEERING (18%)	1	LS		\$ 1,453,000.00
INFLATION @ 5% FOR 2 YEARS	1	LS		\$ 828,000.00
TOTAL				\$ 15,462,000