



200408200118

Skagit County Auditor


8/20/2004 Page 1 of 1 2:52PM

DRINKING WATER SYSTEM STATUS REPORT

I, the undersigned property owner, in making an application for a building permit involving a single-family residence acknowledge that this notice is being signed, notarized and recorded in compliance with Skagit County Code Section 12.48.270 in regards to a drinking water quality parameter that exceeds the maximum contaminant level but is treatable to below the maximum contaminant level.

1. I agree to record this notice with the Skagit County Auditor's Office for the purpose of it being made a part of the record of title.
2. I understand that this notice will appear on any title search or record search, and we have no objection nor will we make claims against Skagit County as a consequence of this recording.
3. The drinking water source for this residential building is located in an area exhibiting hard rock drilling. The inorganic chemistry taken on June 6, 2002 yielded Conductivity and Arsenic levels exceeding the maximum contaminant level (MCL) for drinking water. The levels noted on the date of sampling were: Conductivity 856 (MCL =700 u ohms), Arsenic level of 0.299 (MCL = 0.05 ppm). A Sodium level of 130 mg/l was also detected. While no MCL has been established for Sodium, 200 mg/l is the maximum level recommended for Healthy adults. High levels of sodium may cause health problems for infants and people with cardiac, circulatory or renal diseases. The American Heart Association recommends a maximum level of 20 mg/l for individuals needing to reduce their salt intake. This drinking water source is treated to yield drinking water below the MCL via an Adedage #1354 iron oxide adsorption media treatment device installed on the house plumbing for all inside and outside taps. On August 21, 2004, post treatment results were 17ppm Conductivity, 0.006ppm Arsenic. The Health Officer recommends that property owners exercise caution in the use of this drinking water system by:
 - a. conserving drinking water use where possible by installing low water use fixtures and limiting landscape watering,
 - b. testing for conductivity, arsenic and sodium on a regular interval as recommended by the manufacturer or at a minimum annually, and
 - c. providing appropriate maintenance to the treatment unit as directed by the manufacturer.
4. Water systems with filed status reports will not be used for the creation of new lots.
5. Specific drinking water system information for this lot may be available at the Skagit County Planning and Permit Center.

LEGAL DESCRIPTION: P 116938 (House lot)
 SITE ADDRESS: 21247 Alderbrook, Mount Vernon, WA 98274
 PARCEL NUMBER: P 116938 (Well lot)
 ASSESSOR'S ACCOUNT NO: 330403-1-001-0400
 OWNER (PRINT NAME): Tod and Heather Jones
 MAILING ADDRESS: 3144 Mohawk, Mt. Vernon, WA 98273
 OWNER (SIGNATURE): *Tod Jones*



Subscribed and sworn before me this 20th day of Aug, 2004
 Notary Public in and for the State of Washington.

Tisha Campbell Residing at Mount Vernon WA

UNOFFICIAL COPY