

Here are the results from Wednesday, May 26 sampling. This sampling occurred between storms and fecal coliform numbers were low in most of the river and stream sites, but higher in the drainage infrastructure.

**Results from Wednesday, May 26, 2010**

<b>River Sites</b>		Result	Duplicate
Samish River at Hwy 9	11	50	30
Samish River at upper Prairie Rd	SAM3PR	50	
Samish River above Parsons Creek	SAMPAR	30	
Samish River at Double Creek Ln	SAMDCL	30	
Samish River at first Prairie Rd	SAM1PR	70	
Samish River at Grip Road	SAMGRIP	30	
Samish River at Thomas Rd	32	80	23
<b>Drainage Sites</b>			
Alice Bay Pump Station	33	50	
Edison Slough at School	36	220	
Edison Pump Station	37	240	
North Edison Pump Station	38	170	
<b>Tributaries</b>			
Parsons Creek at mouth	PAR	70	
Skarrup Creek at Double Cr Ln	SKAR	500	
Swede Creek at Grip Rd	8	70	
Weir Creek at Prairie Rd	WCPR	500	
Friday Creek at Prairie Rd	6	50	
Thomas Creek at Hwy 99	3	130	
Thomas Creek at F&S Grade Road	4	1600	
Colony Creek at Colony Rd	39	110	

Rick Haley  
 Water Quality Analyst  
 Skagit County Public Works  
 Water Resources Management  
 1800 Continental Place  
 Mt. Vernon, WA 98273  
[rickh@co.skagit.wa.us](mailto:rickh@co.skagit.wa.us)  
 360-336-9400