

This week's sampling in the Samish Basin took place in two trips due to shortage of time and wanting to wait for rainfall for the PIC sites.

We sampled Skagit County's regular stations on Wednesday, October 13. The pertinent results:

Skagit County sampling in Samish Basin, 10/13/10

Location	Site Number	Result	Duplicate
Samish River at Hwy 9	11	13	
Swede Creek at Grip Rd	8	23	
Samish River at Thomas Rd	32	23	50
Thomas Creek at F&S Grade Rd	4	170	
Thomas Creek at Hwy 99	3	170	
Alice Bay Pump Station	33	80	
Edison Slough at School	36	90	
Edison Pump Station (near bakery)	37	170	
North Edison Pump Station	38	130	
Colony Creek at Colony Rd	39	22	

Nice and low in most locations.

The PIC sites in the middle reaches of the Samish were sampled on Friday, October 15 despite the lack of promised precipitation. Results will be reported next week.

Rick Haley
Water Quality Analyst
Skagit County Public Works
Water Resources Management
1800 Continental Place
Mt. Vernon, WA 98273
rickh@co.skagit.wa.us
360-419-3424 (desk)
360-336-9400 (Public Works receptionist)