

Due to holiday and furlough last week and many meetings this week, just now getting around to putting last week's (11-9) sampling results together. This was a regularly-scheduled (aka ambient) sampling trip, occurred on the falling leg of the hydrograph after a rise in the river on 11-8. Results mostly acceptable except North Edison.

Location	Site Number	Result	Duplicate
Thomas Creek at Hwy 99	3	300	
Thomas Creek at F&S Grade Rd	4	130	
Friday Creek at Prairie Rd	6	30	
Swede Creek at Grip Rd	8	30	
Samish River at Upper Prairie Rd	SAM3PR	8	
Samish River above Parsons Creek	SAMPAR	50	
Samish River at Double Creek Ln	SAMDCL	50	
Samish River at Grip Road	SAMGRIP	70	
Samish River at Hwy 99	SAMH99	23	
Samish River at Thomas Rd	32	130	130
Parsons Creek at mouth	PAR	2	
Colony Creek at Colony Rd	39	80	
Alice Bay Pump Station	33	240	
Edison Slough at School	36	30	
Edison Pump Station	37	30	
North Edison Pump Station	38	1700	

Rick Haley  
 Water Quality Analyst  
 Skagit County Public Works  
 Water Resources Management  
 1800 Continental Place  
 Mt. Vernon, WA 98273  
[rickh@co.skagit.wa.us](mailto:rickh@co.skagit.wa.us)  
 360-419-3424 (desk)  
 360-336-9400 (Public Works receptionist)